

NCI Reference

This volume lists all of the Gcodes that are output in the NCI file. It is divided into two main sections:

- ❖ **NCI Gcodes**page 2
- ❖ **Tool information (2000s parameters)**page 95

Changes for X9

Mastercam X9 includes the following NCI changes:

- Added Mill-Turn **tool_op\$** codes for 230–236.
- Added new parameter to 1016 line for **nesting_op_id\$**.
- New parameters 22–27 have been added to the 20004 line. In addition, two new tool types have been defined, for thread mills and barrel mills.
- New parameter 9 has been added to 20006 line.

Corrections

For NCI 100, the references to **drill_depth_x\$, drill_depth_y\$** and **drill_depthz\$** have been corrected to **drl_depth_x\$, drl_depth_y\$** and **drl_depthz\$**.

The documentation for the 20004–20007 lines has been generally revised and updated.

In addition, we have substantially improved the documentation in this volume for some of the lathe tool information lines: 20101, 20104, 20105 and 20111.

Note that for X9, the old *NCI & Parameter Reference* volume has been broken out into three separate books:

- *NCI Reference* (this book)
- *Operation Parameter Reference*
- *Working with Parameters* application guide.

The *Working with Parameters* application guide collects the “how-to” information on working with operation parameters and NCI data. It presents this content in an easier-to-use format that is better suited for learning or training purposes. The other two volumes only contain tables of reference information and should be easier to use by being smaller and more focused.

NCI Gcodes

This section lists all of the NCI Gcodes used by Mastercam.

- Each entry is preceded by a lettered code indicating which product(s) the entry applies to.
- The table following each entry lists the predefined post variables used to store each parameter.

Control Flags Parameters are detailed in a separate section on page 91.

M R 0 : Linear Move at rapid rate

Definition: 0
 1 2 3 4 5 6

| | | | | |
|---|---------------------|--------------------|----------|---|
| 1 | Cutter compensation | cc\$ | 0 | Cutter compensation modal (no change) |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | |
| 3 | Y position | ynci\$, y\$ | | |
| 4 | Z position | znci\$, z\$ | | |
| 5 | Feed rate | fr\$ | Positive | Feed rate in units per minute |
| | | | -1 | Unchanged |
| | | | -2 | Rapid |
| 6 | Control flags | cur_cfg\$ | | See Control Flags Parameters on page 91. |

L 0 : Linear Move at rapid rate

Definition: 0
1 2 3 4 5 6

| | | | | | |
|---|---------------------|--------------------|----------|---|---|
| 1 | Cutter compensation | cc\$ | | 0 | Cutter compensation modal (no change) |
| | | | | 40 | Cancel cutter compensation in the control |
| | | | | 41 | Cutter compensation in the control = left |
| | | | | 42 | Cutter compensation in the control = right |
| | | | | 140 | Cancel cutter compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | | |
| 3 | Y position | ynci\$, y\$ | | | |
| 4 | Z position | znci\$, z\$ | | | |
| 5 | Feed rate | fr\$ | Positive | Feed rate in units per minute | |
| | | | Negative | Feed rate in units per revolution | |
| 6 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. | |

W 0 : Linear move at rapid rate

Definition: 0
1 2 3 4 5 6 7 8 9

| | | | | | |
|---|--------------------|--------------------|----------|-----|---|
| 1 | Wire compensation | cc\$ | | 0 | Wire compensation modal (no change) |
| | | | | 40 | Cancel wire compensation in the control |
| | | | | 41 | Wire compensation in the control = left |
| | | | | 42 | Wire compensation in the control = right |
| | | | | 140 | Cancel wire compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | | |
| 3 | Y position | ynci\$, y\$ | | | |
| 4 | Z position | znci\$, z\$ | | | |
| 5 | Feed rate | fr\$ | Positive | | Feed rate in units per minute |
| | | | -1 | | Unchanged |
| 6 | Wire taper | wt\$ | | | |
| 7 | Corner type | wc\$ | | 0 | Conical |
| | | | | 1 | Sharp |
| | | | | 2 | Constant |
| | | | | 3 | Other |
| | | | | 4 | Fixed |
| | | | | 5 | Fishtail |
| 8 | Control flags | cur_flg\$ | | | See Control Flags Parameters on page 91. |
| 9 | Corner type radius | wc_rad\$ | | | |

M R 1 : Linear Move at feed rate

Definition: 1
1 2 3 4 5 6

| | | | | |
|---|---------------------|--------------------|----------------------|---|
| 1 | Cutter compensation | cc\$ | | 0 Cutter compensation modal (no change) 40 Cancel cutter compensation in the control 41 Cutter compensation in the control = left 42 Cutter compensation in the control = right 140 Cancel cutter compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | |
| 3 | Y position | ynci\$, y\$ | | |
| 4 | Z position | znci\$, z\$ | | |
| 5 | Feed rate | fr\$ | Positive -1 -2 | Feed rate in units per minute Unchanged Rapid |
| 6 | Control flags | cur_cflg\$ | | See Control Flags Parameters on page 91. |

L 1 : Linear Move at feed rate

Definition: 1
1 2 3 4 5 6

| | | | | |
|---|---------------------|--------------------|----------|---|
| 1 | Cutter compensation | cc\$ | 0 | Cutter compensation modal (no change) |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | |
| 3 | Y position | ynci\$, y\$ | | |
| 4 | Z position | znci\$, z\$ | | |
| 5 | Feed rate | fr\$ | Positive | Feed rate in units per minute |
| | | | Negative | Feed rate in units per revolution |
| 6 | Control flags | cur_cflg\$ | | See Control Flags Parameters on page 91. |

W 1 : Linear move at feed rate

Definition: 1
1 2 3 4 5 6 7 8 9

| | | | | |
|---|--------------------|--------------------|----------------|---|
| 1 | Wire compensation | cc\$ | | 0 Wire compensation modal (no change) 40 Cancel wire compensation in the control 41 Wire compensation in the control = left 42 Wire compensation in the control = right 140 Cancel wire compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | |
| 3 | Y position | ynci\$, y\$ | | |
| 4 | Z position | znci\$, z\$ | | |
| 5 | Feed rate | fr\$ | Positive -1 | Feed rate in units per minute Unchanged |
| 6 | Wire taper | wt\$ | | |
| 7 | Corner type | wc\$ | | 0 Conical 1 Sharp 2 Constant 3 Other 4 Fixed 5 Fishtail |
| 8 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 9 | Corner type radius | wc_rad\$ | | |

M L R 2 : Arc Move CW

Definition: 2
1 2 3 4 5 6 7 8 9 10

| | | | | |
|----|----------------------------|-----------------------|----------|---|
| 1 | Plane position | plane\$ | 0 | XY plane |
| | | | 1 | YZ plane |
| | | | 2 | XZ plane |
| 2 | Cutter compensation | cc\$ | 0 | Cutter compensation modal (no change) |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 3 | X position | xnci\$, x\$ | | |
| 4 | Y position | ynci\$, y\$ | | |
| 5 | Absolute X axis arc center | xc\$ | | (relative to plane) |
| 6 | Absolute Y axis arc center | yc\$ | | (relative to plane) |
| 7 | Z position | znci\$, z\$ | | |
| 8 | Feed rate | fr\$ | Positive | Feed rate per minute |
| | | | Negative | Feed rate per revolution |
| | | | -1 | Unchanged |
| | | | -2 | Rapid |
| 9 | Control flags | cur_cflg\$ | | See Control Flags Parameters on page 91. |
| 10 | Full arc flag | full_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

W 2 : Arc move clockwise

Definition: 2
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

| | | | | |
|----|----------------------------|-----------------------|----------|--|
| 1 | Plane | plane\$ | | This is set, but is never actually used since the plane in Wire is always TOP. |
| 2 | Wire compensation | cc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 3 | X position | xnci\$, x\$ | | |
| 4 | Y position | ynci\$, y\$ | | |
| 5 | Absolute X-axis arc center | xc\$ | | (relative to plane) |
| 6 | Absolute Y-axis arc center | yc\$ | | (relative to plane) |
| 7 | Z position | znci\$, z\$ | | |
| 8 | Feed rate | fr\$ | Positive | Feed rate per minute |
| | | | -1 | Unchanged |
| 9 | Wire taper | wt\$ | | |
| 10 | Corner type | wc\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fishtail |
| 11 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 12 | Corner radius | wc_rad\$ | | |
| 13 | Arc type | warc_ctyp\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fish Tail |
| 14 | Arc radius | warc_rad\$ | | |
| 15 | Full arc flag | full_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

M L R 3 : Arc Move CCW

Definition: 3
1 2 3 4 5 6 7 8 9 10

| | | | | |
|----|----------------------------|-----------------------|----------|---|
| 1 | Plane position | plane\$ | 0 | XY plane |
| | | | 1 | YZ plane |
| | | | 2 | XZ plane |
| 2 | Cutter compensation | cc\$ | 0 | Cutter compensation modal (no change) |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 3 | X position | xnci\$, x\$ | | |
| 4 | Y position | ynci\$, y\$ | | |
| 5 | Absolute X axis arc center | xc\$ | | (relative to plane) |
| 6 | Absolute Y axis arc center | yc\$ | | (relative to plane) |
| 7 | Z position | znci\$, z\$ | | |
| 8 | Feed rate | fr\$ | Positive | Feed rate per minute |
| | | | Negative | Feed rate per revolution |
| | | | -1 | Unchanged |
| | | | -2 | Rapid |
| 9 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 10 | Full arc flag | full_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

W 3 : Arc move counterclockwise

Definition: 3
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

| | | | | |
|----|----------------------------|-----------------------|----------|--|
| 1 | Plane | plane\$ | 0 | This is set, but is never actually used since the plane in Wire is always TOP. |
| 2 | Wire compensation | cc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 3 | X position | xnci\$, x\$ | | |
| 4 | Y position | ynci\$, y\$ | | |
| 5 | Absolute X-axis arc center | xc\$ | | (relative to plane) |
| 6 | Absolute Y-axis arc center | yc\$ | | (relative to plane) |
| 7 | Z position | znci\$, z\$ | | |
| 8 | Feed rate | fr\$ | Positive | Feed rate per minute |
| | | | -1 | Unchanged |
| 9 | Wire taper | wt\$ | | |
| 10 | Corner type | wc\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fishtail |
| 11 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 12 | Corner radius | wc_rad\$ | | |
| 13 | Arc type | warc_ctyp\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fish Tail |
| 14 | Arc radius | warc_rad\$ | | |
| 15 | Full arc flag | full_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

M R 4 : Dwell and Spindle Change

Definition: 4
1 2 3

| | | | |
|---|---------------|---------------|----------------------|
| 1 | Dwell | dwel\$ | Dwell time |
| 2 | Spindle speed | ss\$ | Spindle speed in RPM |
| 3 | (not used) | | |

L 4 : Dwell and Spindle Change

Definition: 4
1 2 3

| | | | | |
|---|-------------------|----------------|----------|---|
| 1 | Dwell | dwell\$ | | Dwell time |
| 2 | Spindle speed | ss\$ | Positive | Spindle speed in RPM |
| | | | 0 | Spindle stop |
| 3 | Spindle direction | spdir\$ | Negative | Spindle speed in surface units per minute |
| | | | -1 | Reverse |
| | | | 0 | Off |
| | | | 1 | Forward |

W 4 : Dwell

Definition: 4
1 2 3

| | | | |
|---|------------|----------------|------------|
| 1 | Dwell | dwell\$ | Dwell time |
| 2 | (Not used) | | |
| 3 | (Not used) | | |

M R 11 : 5-Axis Move

Definition: 11
1 2 3 4 5 6 7 8 9 10 11 12

| | | | | |
|----|-----------------------|--------------------|-----------|---|
| 1 | X position | xnci\$, x\$ | | |
| 2 | Y position | ynci\$, y\$ | | |
| 3 | Z position | znci\$, z\$ | | |
| 4 | U position | u\$ | | |
| 5 | V position | v\$ | | |
| 6 | W position | w\$ | | |
| 7 | Feed rate | fr\$ | Positive | Feed rate |
| | | | -1 | Unchanged |
| | | | -2 | Rapid |
| 8* | Tool parameters | | <i>nn</i> | left digit = cutpos\$, right digit = cuttp\$ |
| | | cutpos\$ | 10 | Start |
| | | | 20 | Middle |
| | | | 30 | End |
| | | | 40 | Entry to cut |
| | | | 50 | Exit from cut |
| | | | 60 | Safety zone |
| | | cuttp\$ | 1 | Zigzag |
| | | | 2 | One way |
| | | | 3 | Circular |
| | | | 4 | Swarf |
| 9 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 10 | Surface normal vector | p_svec\$ | | |
| 11 | Surface normal vector | q_svec\$ | | |
| 12 | Surface normal vector | r_svec\$ | | |

* These are only maintained for compatibility with older posts. Use the control flags parameter instead!

W 11 : 4-Axis Taper Move

Definition: 11
1 2 3 4 5 6 7 8 9

| | | | | |
|---|-------------------|-------------|-----|---|
| 1 | Wire compensation | cc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | lower point |
| 3 | Y position | ynci\$, y\$ | | lower point |
| 4 | Z position | znci\$, z\$ | | lower point |
| 5 | U position | u\$ | | upper point |
| 6 | V position | v\$ | | upper point |
| 7 | W position | w\$ | | upper point |
| 8 | Feed rate | fr\$ | | Feed rate |
| 9 | Control flags | cur_cflg\$ | | See Control Flags Parameters on page 91. |

W 20 : Direct 4-axis lower guide – linear move at rapid

Definition: 20
1 2 3 4 5 6 7 8 9

| | | | | |
|---|--------------------|--------------------|----------------|---|
| 1 | Wire compensation | cc\$ | | 0 Wire compensation modal (no change) 40 Cancel wire compensation in the control 41 Wire compensation in the control = left 42 Wire compensation in the control = right 140 Cancel wire compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | |
| 3 | Y position | ynci\$, y\$ | | |
| 4 | Z position | znci\$, z\$ | | |
| 5 | Feed rate | fr\$ | Positive -1 | Feed rate in units per minute Unchanged |
| 6 | Wire taper | wt\$ | | |
| 7 | Corner type | wc\$ | | 0 Conical 1 Sharp 2 Constant 3 Other 4 Fixed 5 Fishtail |
| 8 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 9 | Corner type radius | wc_rad\$ | | |

W 21 : Direct 4-axis lower guide – linear move at feed rate

Definition: 21
1 2 3 4 5 6 7 8 9

| | | | | |
|---|--------------------|--------------------|----------------|---|
| 1 | Wire compensation | cc\$ | | 0 Wire compensation modal (no change) 40 Cancel wire compensation in the control 41 Wire compensation in the control = left 42 Wire compensation in the control = right 140 Cancel wire compensation last move in the contour |
| 2 | X position | xnci\$, x\$ | | |
| 3 | Y position | ynci\$, y\$ | | |
| 4 | Z position | znci\$, z\$ | | |
| 5 | Feed rate | fr\$ | Positive -1 | Feed rate in units per minute Unchanged |
| 6 | Wire taper | wt\$ | | |
| 7 | Corner type | wc\$ | | 0 Conical 1 Sharp 2 Constant 3 Other 4 Fixed 5 Fishtail |
| 8 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 9 | Corner type radius | wc_rad\$ | | |

W 22 : Direct 4-axis lower guide – arc move clockwise

Definition: 22
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

| | | | | |
|----|----------------------------|-----------------------|----------|--|
| 1 | Plane | plane\$ | 0 | This is set, but is never actually used since the plane in Wire is always TOP. |
| 2 | Wire compensation | cc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 3 | X position | xnci\$, x\$ | | |
| 4 | Y position | ynci\$, y\$ | | |
| 5 | Absolute X-axis arc center | xc\$ | | (relative to plane) |
| 6 | Absolute Y-axis arc center | yc\$ | | (relative to plane) |
| 7 | Z position | znci\$, z\$ | | |
| 8 | Feed rate | fr\$ | Positive | Feed rate per minute |
| | | | -1 | Unchanged |
| 9 | Wire taper | wt\$ | | |
| 10 | Corner type | wc\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fishtail |
| 11 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 12 | Corner radius | wc_rad\$ | | |
| 13 | Arc type | warc_ctyp\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fish Tail |
| 14 | Arc radius | warc_rad\$ | | |
| 15 | Full arc flag | full_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

W 23 : Direct 4-axis lower guide – arc move counterclockwise

Definition: 23
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

| | | | | |
|----|----------------------------|-----------------------|----------|--|
| 1 | Plane | plane\$ | 0 | This is set, but is never actually used since the plane in Wire is always TOP. |
| 2 | Wire compensation | cc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 3 | X position | xnci\$, x\$ | | |
| 4 | Y position | ynci\$, y\$ | | |
| 5 | Absolute X-axis arc center | xc\$ | | (relative to plane) |
| 6 | Absolute Y-axis arc center | yc\$ | | (relative to plane) |
| 7 | Z position | znci\$, z\$ | | |
| 8 | Feed rate | fr\$ | Positive | Feed rate per minute |
| | | | -1 | Unchanged |
| 9 | Wire taper | wt\$ | | |
| 10 | Corner type | wc\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fishtail |
| 11 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 12 | Corner radius | wc_rad\$ | | |
| 13 | Arc type | warc_ctyp\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fish Tail |
| 14 | Arc radius | warc_rad\$ | | |
| 15 | Full arc flag | full_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

W 30 : Direct 4-axis upper guide – linear move at rapid

Definition: 30
1 2 3 4 5 6 7 8 9

| | | | | |
|---|--------------------|-------------------|----------------|---|
| 1 | Wire compensation | cc\$ | | 0 Wire compensation modal (no change) 40 Cancel wire compensation in the control 41 Wire compensation in the control = left 42 Wire compensation in the control = right 140 Cancel wire compensation last move in the contour |
| 2 | X position | wx\$ | | |
| 3 | Y position | wy\$ | | |
| 4 | Z position | wz\$ | | |
| 5 | Feed rate | wfr\$ | Positive -1 | Feed rate in units per minute Unchanged |
| 6 | Wire taper | wtp\$ | | |
| 7 | Corner type | wcor\$ | | 0 Conical 1 Sharp 2 Constant 3 Other 4 Fixed 5 Fishtail |
| 8 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 9 | Corner type radius | wcor_rad\$ | | |

W 31 : Direct 4-axis upper guide – linear move at feed rate

Definition: 31
1 2 3 4 5 6 7 8 9

| | | | | |
|---|--------------------|------------------------|----------------|--|
| 1 | Wire compensation | cc\$ | | 0 Wire compensation modal (no change) 40 Cancel wire compensation in the control 41 Wire compensation in the control = left 42 Wire compensation in the control = right 140 Cancel wire compensation last move in the contour |
| 2 | X position | wx\$ | | |
| 3 | Y position | wy\$ | | |
| 4 | Z position | wz\$ | | |
| 5 | Feed rate | wfr\$ | Positive -1 | Feed rate in units per minute Unchanged |
| 6 | Wire taper | wtp\$ | | |
| 7 | Corner type | wcor\$ | | 0 Conical 1 Sharp 2 Constant 3 Other 4 Fixed 5 Fishtail |
| 8 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 9 | Corner type radius | wcor_rad \$ | | |

W 32 : Direct 4-axis upper guide – arc move clockwise

Definition: 32
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

| | | | | |
|----|----------------------------|----------------------|----------|---|
| 1 | (Not used) | | | |
| 2 | Wire compensation | wcc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 3 | X position | wx\$ | | |
| 4 | Y position | wy\$ | | |
| 5 | Absolute X-axis arc center | wxc\$ | | (relative to plane) |
| 6 | Absolute Y-axis arc center | wyc\$ | | (relative to plane) |
| 7 | Z position | wz\$ | | |
| 8 | Feed rate | wfr\$ | Positive | Feed rate per minute |
| | | | -1 | Unchanged |
| 9 | Wire taper | wtpr\$ | | |
| 10 | Corner type | wcor\$ | | Conical |
| | | | | Sharp |
| | | | | Constant |
| | | | | Other |
| | | | | Fixed |
| | | | | Fishtail |
| 11 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 12 | Corner radius | wcor_rad\$ | | |
| 13 | Arc type | warc_cortyp\$ | | Conical |
| | | | | Sharp |
| | | | | Constant |
| | | | | Other |
| | | | | Fixed |
| | | | | Fish tail |
| 14 | Arc radius | | | |
| 15 | Full arc flag | | | NOT a full arc move |
| | | | | Full arc move (360-degree sweep) |

W 33 : Direct 4-axis upper guide – arc move counterclockwise

Definition: 33
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

| | | | | |
|----|----------------------------|------------------------|----------|---|
| 1 | (Not used) | | | |
| 2 | Wire compensation | wcc\$ | 0 | Wire compensation modal (no change) |
| | | | 40 | Cancel wire compensation in the control |
| | | | 41 | Wire compensation in the control = left |
| | | | 42 | Wire compensation in the control = right |
| | | | 140 | Cancel wire compensation last move in the contour |
| 3 | X position | wx\$ | | |
| 4 | Y position | wy\$ | | |
| 5 | Absolute X-axis arc center | wxc\$ | | (relative to plane) |
| 6 | Absolute Y-axis arc center | wyc\$ | | (relative to plane) |
| 7 | Z position | wz\$ | | |
| 8 | Feed rate | wfr\$ | Positive | Feed rate per minute |
| | | | -1 | Unchanged |
| 9 | Wire taper | wtp\$ | | |
| 10 | Corner type | wcor\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fishtail |
| 11 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 12 | Corner radius | wcor_rad\$ | | |
| 13 | Arc type | warc_cortyp\$ | 0 | Conical |
| | | | 1 | Sharp |
| | | | 2 | Constant |
| | | | 3 | Other |
| | | | 4 | Fixed |
| | | | 5 | Fish tail |
| 14 | Arc radius | warc_radius\$ | | |
| 15 | Full arc flag | wfull_arc_flg\$ | 0 | NOT a full arc move |
| | | | 1 | Full arc move (360-degree sweep) |

L M R W 80 : Cancel Drill / Canned Cycle

Definition: 80
 [blank line]

Note: Even though Gcode 80 has no parameters, a blank line must be output for the second line.

M L R 81 : Start Drill Cycle

Definition: 81
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

| | | | |
|----|------------------------------|----------------------|---|
| 1 | Drill cycle type | drillcyc\$ | 0 Simple 1 Peck 2 Chip break 3 Tap 4 Bore #1 5 Bore #2 6 Misc #1 7 Misc #2 8–19 Custom cycles Calculated variable: drl_cycle\$ |
| 2 | X position | drl_depth_x\$ | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: x\$ |
| 3 | Y position | drl_depth_y\$ | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: y\$ |
| 4 | Z position | drl_depth_z\$ | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: z\$, depth\$ |
| 5 | Dwell time | dwell\$ | |
| 6 | Feed rate | frplunge\$ | |
| 7 | First peck amount | peck1\$ | |
| 8 | Subsequent peck amount | peck2\$ | |
| 9 | Peck clearance | peckclr\$ | |
| 10 | Chip break retract | retr\$ | |
| 11 | Drill cycle initial height | drl_sel_ini\$ | The distance from the selected drill position (zdrl) to the <i>initial</i> height, sign is positive for above selected drill position. Calculated variable: initht\$ |
| 12 | Drill cycle reference height | drl_sel_ref\$ | The distance from the selected drill position (zdrl) to the <i>reference</i> height, sign is positive for above selected drill position. Calculated variable: refht\$ |

| | | | |
|----|-----------------------------------|----------------------|---|
| 13 | Drill depth | drl_sel_tos\$ | The distance from the selected drill position (zdr1) to the <i>top of stock</i> , sign is positive for above selected drill position. Calculated variable: zdr1\$ |
| 14 | Boring bar clearance shift amount | shftdrl\$ | |
| 15 | U position | drl_init_x\$ | UVW is a 3D point that represents the initial height point. Calculated variable: u\$ |
| 16 | V position | drl_init_y\$ | UVW is a 3D point that represents the initial height point. Calculated variable: v\$ |
| 17 | W position | drl_init_z\$ | UVW is a 3D point that represents the initial height point. Calculated variable: w\$ |
| 18 | Control flags | cur_flg\$ | See Control Flags Parameters on page 91. |
| 19 | Drill direction | rev_drl5\$ | Obsolete—no longer used. |
| 20 | Block drill diameter | drl_dia\$ | This is the diameter of the drill that was selected for the hole. For all operations besides Router block drill, this is 0. |

Note: If **vers_no\$** is 8 or greater, the following data is calculated and overwrites the parameter passed in the NCI:

- **depth\$** from **z\$**
- **zdr1\$** (calculated) from **w\$ - initht\$**
- **refht\$** from **zdr1\$** (calculated) + **refht\$**
- **tosz\$** (top of stock) from **zdr1\$** (calculated) + **zdr1\$** (original)
- **initht\$** from **w\$**

W 81 : Start Canned Cycle

Definition: 81
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

| | | | | |
|----|------------------|------------------|------|---|
| 1 | Drill cycle type | cancyc\$ | 0-19 | Custom cycles |
| 2 | X position | xnci\$ | | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: x\$ |
| 3 | Y position | ynci\$ | | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: y\$ |
| 4 | Z position | znci\$ | | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: z\$ |
| 5 | Entered value | canned1\$ | | |
| 6 | | | | <i>(not used for Wire)</i> |
| 7 | Entered value | canned4\$ | | |
| 8 | Entered value | canned5\$ | | |
| 9 | Entered value | canned6\$ | | |
| 10 | Entered value | canned7\$ | | |
| 11 | Entered value | canned2\$ | | |
| 12 | Entered value | canned3\$ | | |
| 13 | | | | <i>(not used for Wire)</i> |
| 14 | | | | <i>(not used for Wire)</i> |
| 15 | | | | <i>(not used for Wire)</i> |
| 16 | | | | <i>(not used for Wire)</i> |
| 17 | | | | <i>(not used for Wire)</i> |
| 18 | Control flags | cur_flg\$ | | See Control Flags Parameters on page 91. |
| 19 | | | | <i>(not used for Wire)</i> |

L M R W 82 : Additional Drill / Canned Cycle Parameters

Definition: 82
1 2 3 4 5 6 7 8 9 10

| | | | |
|----|--------------------|-------------|--|
| 1 | Drill parameter 1 | drl_prm1\$ | |
| 2 | Drill parameter 2 | drl_prm2\$ | |
| 3 | Drill parameter 3 | drl_prm3\$ | |
| 4 | Drill parameter 4 | drl_prm4\$ | |
| 5 | Drill parameter 5 | drl_prm5\$ | |
| 6 | Drill parameter 6 | drl_prm6\$ | |
| 7 | Drill parameter 7 | drl_prm7\$ | |
| 8 | Drill parameter 8 | drl_prm8\$ | |
| 9 | Drill parameter 9 | drl_prm9\$ | |
| 10 | Drill parameter 10 | drl_prm10\$ | |

NOTE: The **drl_prm** variables do not have a pre-defined meaning. The post can be customized to use these for whatever purpose is desired for that cycle.

R 83 : Block Drill / Canned Cycle Parameters

Definition: 83
1 2 3 4 5 6 7 8 9 10 11 12

| | | | |
|----|--|------------------------|---|
| 1 | Drill point (X) position at depth. | bdrl_x\$ | Position of the <i>lead</i> tool |
| 2 | Drill point (Y) position at depth. | bdrl_y\$ | Position of the <i>lead</i> tool |
| 3 | Drill point (Z) position at depth. | bdrl_z\$ | Position of the <i>lead</i> tool |
| 4 | Offset to lead tool in X | bdrl_ofs_x\$ | Distance of drill hole to the lead drill position. |
| 5 | Offset to lead tool in Y | bdrl_ofs_y\$ | Distance of drill hole to the lead drill position. |
| 6 | Offset to lead tool. In Z | bdrl_ofs_z\$ | Distance of drill hole to the lead drill position. |
| 7 | Tool group number | bdrl_tool_grp\$ | |
| 8 | Work offset number | bdrl_wrk_ofs\$ | |
| 9 | Position of lead drill at initial height. | bdrl_u\$ | Clearance point position in X |
| 10 | Position of lead drill at initial height. | bdrl_v\$ | Clearance point position in Y |
| 11 | Position of lead drill at initial height. | bdrl_w\$ | Clearance point position in Z |
| 12 | Number(s) of the stations whose drills have dropped. | bdrl_tool_no\$ | This is a bitwise operator where each bit represents a station on the block. See bdrl_tool_no\$ to learn more. |

Note: MP also reads the following variables when block drilling is active: **bdrl_x2\$**, **bdrl_y2\$**, and **bdrl_z2\$**. These three values are actually read from NCI **M L R 81 : Start Drill Cycle** and **M L R 100 : Canned Cycle Repeat Position** data records. They are the actual drilled location (which may not be the lead tool position) at depth.

M L R 100 : Canned Cycle Repeat Position

Definition: 100
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22
 23 24

| | | | |
|----|------------------------------|---------------|--|
| 1 | (Not used) | | |
| 2 | X position | drl_depth_x\$ | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: x\$ |
| 3 | Y position | drl_depth_y\$ | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: y\$ |
| 4 | Z position | drl_depth_z\$ | XYZ is a 3D point that represents the drill point at the bottom of the hole. Calculated variable: z\$ |
| 5 | Drill cycle initial height | drl_sel_ini\$ | The distance from the selected drill position (zdrl\$) to the <i>initial</i> height, sign is positive for above selected drill position. Calculated variable: initht\$ |
| 6 | Drill cycle reference height | drl_sel_ref\$ | The distance from the selected drill position (zdrl\$) to the <i>reference</i> height, sign is positive for above selected drill position. Calculated variable: refht\$ |
| 7 | Dwell time | dwell\$ | |
| 8 | Feed rate | frplunge\$ | |
| 9 | U position | drl_init_x\$ | UVW is a 3D point that represents the initial height point. Calculated variable: u\$ |
| 10 | V position | drl_init_y\$ | UVW is a 3D point that represents the initial height point. Calculated variable: v\$ |
| 11 | W position | drl_init_z\$ | UVW is a 3D point that represents the initial height point. Calculated variable: w\$ |
| 12 | Control flags | cur_cfg\$ | See Control Flags Parameters on page 91. |
| 13 | Drill depth | rev_drl5\$ | Obsolete—no longer used. |
| 14 | Top of stock | drl_sel_tos\$ | The distance from the selected drill position (zdrl\$) to the <i>top of stock</i> , sign positive for above zdrl\$ |

| | | | |
|----|----------------------|------------------|---|
| 15 | Drilling matrix | drl_m1\$ | X-axis vector (x) |
| 16 | | drl_m2\$ | X-axis vector (y) |
| 17 | | drl_m3\$ | X-axis vector (z) |
| 18 | | drl_m4\$ | Y-axis vector (x) |
| 19 | | drl_m5\$ | Y-axis vector (y) |
| 20 | | drl_m6\$ | Y-axis vector (z) |
| 21 | | drl_m7\$ | Z-axis vector (x) |
| 22 | | drl_m8\$ | Z-axis vector (y) |
| 23 | | drl_m9\$ | Z-axis vector (z) |
| 24 | Block drill diameter | drl_dia\$ | This is the diameter of the drill that was selected for the hole. For all operations besides Router block drill, this is 0. |

When the NCI 81 line is read, the tool plane matrix (**m1\$–m9\$**) is copied from the NCI 1014 data to the **drl_m1\$–drl_m9\$** matrix.

This matrix (**drl_m1\$–drl_m9\$**) is then copied to the tool plane matrix (**m1\$–m9\$**) when the NCI 100 line is read.

W 100 : Canned Cycle Repeat Position

Definition: **100**
 1 2 3 4 5

| | | |
|---|------------|--------------------|
| 1 | (Not used) | |
| 2 | X position | xnci\$, x\$ |
| 3 | Y position | ynci\$, y\$ |
| 4 | Z position | znci\$, z\$ |
| 5 | (Not used) | |

L 200 : Threading Parameters One

Definition: 200
1 2 3 4 5 6 7 8

| | | | |
|---|---------------------------------|---------------------|---|
| 1 | Number of spring cuts | nspring\$ | |
| 2 | Finish allowance | thdfinish\$ | |
| 3 | Anticipated thread pull-off | thdpulloff\$ | |
| 4 | Number of starts | nstarts\$ | |
| 5 | Clearance perpendicular to cuts | thdxclr\$ | |
| 6 | Thread infeed angle | thdangle\$ | Value in radians |
| 7 | Equal depth thread cuts | thdeqcut\$ | 0 Determine depth cuts from: Equal area method. 1 Determine depth cuts from: Number of cuts. |
| 8 | Number of cuts | thdncuts\$ | >0 Determine number of cuts from: Number of cuts. |

Always appears together with the **L 201 : Threading Parameters Two**.

L 201 : Threading Parameters Two

Definition: 201
1 2 3 4 5 6 7 8 9 10 11 12

| | | | | |
|----|-----------------------|-------------------|----------------------|---|
| 1 | X position 1 | thdx1\$ | | Thread major |
| 2 | X position 2 | thdx2\$ | | Thread minor |
| 3 | Z position 1 | thdz1\$ | | Starting Z position of thread |
| 4 | Z position 2 | thdz2\$ | | Ending Z position of thread |
| 5 | Lead settings | thdlead\$ | Positive Negative | Lead in units per thread Lead in threads per inch |
| 6 | Amount of first cut | thdfirst\$ | | Calculated based on thdequcut\$ |
| 7 | Amount of last cut | thdlast\$ | | |
| 8 | Stock clearance in Z | thdzclr\$ | | Acceleration clearance |
| 9 | Thread angle | thda1\$ | | Value in radians |
| 10 | Thread included angle | thda2\$ | | Value in radians |
| 11 | Thread type settings | thdtype\$ | 0 1 2 3 | Longhand cycle—example, G32 Canned cycle—example, G76 Box thread—example, G92 Alternating—example, G32 |
| 12 | X position 3 | thdx3\$ | | Ending X position of thread |

Always appears together with the **L 200 : Threading Parameters One**.

- **thdlead\$** is always converted to a (positive) units-per-thread value.
- Calculate thread taper by **(thdx\$2 – thdx\$3)**.

L 900 : Stock Transfer – Misc Ops function

Definition: 900
1 2 3 4 5 6 7 8 9 10 11

| | | | | |
|----|--------------------------------------|---------------------------|--------|--|
| 1 | Active spindle for stock to transfer | stck_spindle\$ | 0 1 | Main spindle Sub spindle |
| 2 | | stck_init_z\$ | | Z coordinate on stock to be transferred |
| 3 | | stck_final_z\$ | | Z coordinate on transferred stock |
| 4 | | stck_chuk_st_z\$ | | Source chuck Z axis reference position <i>before</i> transfer |
| 5 | | stck_chuk_st_x\$ | | Source chuck X axis reference position <i>before</i> transfer |
| 6 | | stck_chuk_end_z\$ | | Source chuck Z axis reference position <i>after</i> transfer |
| 7 | | stck_chuk_end_x\$ | | Source chuck X axis reference position <i>after</i> transfer |
| 8 | | stck_chuk_st_dz\$ | | Destination chuck Z axis reference position <i>before</i> transfer |
| 9 | | stck_chuk_st_dx\$ | | Destination chuck X axis reference position <i>before</i> transfer |
| 10 | | stck_chuk_end_dz\$ | | Destination chuck Z axis reference position <i>after</i> transfer |
| 11 | | stck_chuk_end_dx\$ | | Destination chuck X axis reference position <i>after</i> transfer |

Processed by postblock **pstck_trans\$**.

L 901 : Stock Flip – Misc Ops function

Definition: 901
1 2 3 4 5 6 7

| | | | | |
|---|--------------------------------------|--------------------------|--------|--|
| 1 | Active spindle for stock to transfer | stck_spindle\$ | 0 1 | Main spindle Sub spindle |
| 2 | | stck_init_z\$ | | Z coordinate on stock <i>before</i> flip |
| 3 | | stck_final_z\$ | | Z coordinate on stock <i>after</i> flip |
| 4 | | stck_chuk_st_z\$ | | Chuck Z axis position <i>before</i> flip |
| 5 | | stck_chuk_st_x\$ | | Chuck X axis position <i>before</i> flip |
| 6 | | stck_chuk_end_z\$ | | Chuck Z axis position <i>after</i> flip |
| 7 | | stck_chuk_end_x\$ | | Chuck X axis position <i>after</i> flip |

Processed by postblock **pstck_flip\$**.

L 902 : Stock Advance – Misc Ops function

Definition: 902
1 2 3 4 5 6 7 8 9 10 11 12 13

| | | | | |
|----|--------------------------------------|--------------------------|-------------|--|
| 1 | Active spindle for stock to transfer | stck_spindle\$ | 0 1 | Main spindle Sub spindle |
| 2 | | stck_op\$ | 0 1 2 | Push stock Push stock with Use Tool Stop option Pull stock |
| 3 | | stck_clear\$ | | Stock clearance (pull stock method) |
| 4 | | stck_grip\$ | | Grip length (pull stock method) |
| 5 | | stck_tool_x\$ | | Tool X axis position for bar stop/puller |
| 6 | | stck_init_z\$ | | Z coordinate of stock <i>before</i> advance |
| 7 | | stck_final_z\$ | | Z coordinate of stock <i>after</i> advance |
| 8 | | stck_appr_fr\$ | | Feed rate that the bar puller uses while moving into position |
| 9 | | stck_adv_fr\$ | | Feed rate that the stock advances at |
| 10 | | stck_chuk_st_z\$ | | Chuck Z axis position <i>before</i> advance |
| 11 | | stck_chuk_st_x\$ | | Chuck X axis position <i>before</i> advance |
| 12 | | stck_chuk_end_z\$ | | Chuck Z axis position <i>after</i> advance |
| 13 | | stck_chuk_end_x\$ | | Chuck X axis position <i>after</i> advance |

Processed by postblock **pstck_bar_fd\$**.

L 903 : Chuck – Misc Ops function

Definition: 903
1 2 3 4 5 6

| | | | | |
|---|----------------------------------|--------------------------|---|-------------------------------------|
| 1 | Active spindle for clamp/unclamp | clmp_spindle\$ | 0 | Main spindle |
| | | | 1 | Subspindle |
| 2 | Chuck action | clmp_op\$ | 0 | Clamp |
| | | | 1 | Un-clamp |
| | | | 2 | Re-position |
| | | | 3 | Eject stock (<i>added for X5</i>) |
| 3 | | stck_chuk_st_z\$ | | Original Z-axis chuck position |
| 4 | | stck_chuk_st_x\$ | | Original X-axis chuck position |
| 5 | | stck_chuk_end_z\$ | | Final Z-axis chuck position |
| 6 | | stck_chuk_end_x\$ | | Final X-axis chuck position |

L 904 : TailStock – Misc Ops function

Definition: 904
1 2 3

| | | | | |
|---|-----------|-----------------------|---|---------------------------------|
| 1 | Operation | tlstck_on\$ | 0 | Retract tailstock |
| | | | 1 | Engage tailstock |
| 2 | | stck_init_z\$ | | Initial Z position of tailstock |
| 3 | | stck_final_z\$ | | Final Z position of tailstock |

L 905 : SteadyRest – Misc Ops function

Definition: 905
 1 2

| | | |
|---|-----------------------|------------------------------|
| 1 | stck_init_z\$ | Initial steady rest position |
| 2 | stck_final_z\$ | Final steady rest position |

Processed by postblock **psteadyrest\$**.

L 911 : Define Misc Ops custom parameters — reals

Definition: 911
1 2 3 4 5 6 7 8 9 10

| | | | |
|----|-----------------------|-----------------------|--|
| 1 | Miscellaneous real 1 | miscops_mr1\$ | |
| 2 | Miscellaneous real 2 | miscops_mr2\$ | |
| 3 | Miscellaneous real 3 | miscops_mr3\$ | |
| 4 | Miscellaneous real 4 | miscops_mr4\$ | |
| 5 | Miscellaneous real 5 | miscops_mr5\$ | |
| 6 | Miscellaneous real 6 | miscops_mr6\$ | |
| 7 | Miscellaneous real 7 | miscops_mr7\$ | |
| 8 | Miscellaneous real 8 | miscops_mr8\$ | |
| 9 | Miscellaneous real 9 | miscops_mr9\$ | |
| 10 | Miscellaneous real 10 | miscops_mr10\$ | |

L 912 : Define Misc Ops custom parameters — integers

Definition: **912**
 1 2 3 4 5 6 7 8 9 10

| | | | |
|----|--------------------------|-----------------------|--|
| 1 | Miscellaneous integer 1 | miscops_mi1\$ | |
| 2 | Miscellaneous integer 2 | miscops_mi2\$ | |
| 3 | Miscellaneous integer 3 | miscops_mi3\$ | |
| 4 | Miscellaneous integer 4 | miscops_mi4\$ | |
| 5 | Miscellaneous integer 5 | miscops_mi5\$ | |
| 6 | Miscellaneous integer 6 | miscops_mi6\$ | |
| 7 | Miscellaneous integer 7 | miscops_mi7\$ | |
| 8 | Miscellaneous integer 8 | miscops_mi8\$ | |
| 9 | Miscellaneous integer 9 | miscops_mi9\$ | |
| 10 | Miscellaneous integer 10 | miscops_mi10\$ | |

M R L 950 : Axis combination

Definition: **950**
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22
 23 24 25 26

| | | |
|---------------------------|-----------------------|----------------------------------|
| 1 | synclath\$ | |
| 2 | syncbfor\$ | |
| 3 | syncmode\$ | |
| 4 | syncaxis\$ | Component ID of axis combination |
| 5 | syncstream\$ | |
| 6 | syncmodebfor\$ | |
| [all other parameters] | (Not used) | |

M R L W 999 : Start of operation

Definition: 999
1 2 3

New predefined variables for parameters 1 and 3 were introduced for Mastercam X5.

| | | | |
|---|----------------------------------|----------------------|--|
| 1 | Code for specific operation type | synctool_op\$ | Takes the same values as the tool_op\$ operation codes: M R L 1016 : Additional Miscellaneous Parameters on page 68 W 1016 : Additional Miscellaneous Parameters on page 69 |
| 2 | data stream | syncstream\$ | |
| 3 | Operation ID numbers | syncop_id\$ | Takes the same values as op_id\$. |

These let you access the **tool_op\$** and **op_id\$** values before the 1016 line is written.

M R 1000 : Null tool change

Definition: 1000
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

| | | | | |
|----|-----------------------------|------------------|--|--|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Tool number | t\$ | | |
| 5 | Tool diameter offset number | tloffno\$ | | |
| 6 | Tool length offset number | tlingno\$ | | |
| 7 | Plane position | plane\$ | 0 XY plane 1 YZ plane 2 XZ plane | |
| 8 | Spindle speed in RPM | ss\$ | Positive Spindle forward 0 Spindle stop Negative Spindle reverse | |
| 9 | Feed rate | fr\$ | | |
| 10 | Coolant use | coolant\$ | 0 Off 1 Flood 2 Mist 3 Tool | |
| 11 | X rapid position | xr\$ | | |
| 12 | Y rapid position | yr\$ | | |
| 13 | Z rapid position | zr\$ | | |
| 14 | X home position | xh\$ | | |
| 15 | Y home position | yh\$ | | |
| 16 | Z home position | zh\$ | | |
| 17 | Axis substitution | rotaxis\$ | -2 Axis substitution, substitute Y, CCW -1 Axis substitution, substitute X, CCW 0 None 1 Axis substitution, substitute X, CW 2 Axis substitution, substitute Y, CW 11 Polar conversion, rotate about X 12 Polar conversion, rotate about Y 13 Polar conversion, rotate about Z 21 4-axis, rotate about X 22 4-axis, rotate about Y 23 4-axis, rotate about Z | |

| | | | |
|----|-----------------------------------|-----------------|--|
| 18 | Diameter for axis substitution | rotdia\$ | |
|----|-----------------------------------|-----------------|--|

L 1000 : Null tool change

Definition: 1000
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

| | | | | |
|----|-----------------------------|------------------|---------------------------|---|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Tool number | t\$ | | |
| 5 | Tool diameter offset number | tloffno\$ | | |
| 6 | Maximum spindle speed | maxss\$ | | |
| 7 | Tool orientation | orient\$ | | |
| 8 | Spindle speed | ss\$ | Positive 0 Negative | Spindle speed in RPM Spindle stop Spindle speed in surface units per minute |
| 9 | Feed rate | fr\$ | Positive Negative | Feed rate in units per minute Feed rate in units per revolution |
| 10 | Coolant use | coolant\$ | 0 1 2 3 | Off Flood Mist Tool |
| 11 | X rapid position | xr\$ | | |
| 12 | Y rapid position | yr\$ | | |
| 13 | Z rapid position | zr\$ | | |
| 14 | X home position | xh\$ | | |
| 15 | Y home position | yh\$ | | |
| 16 | Z home position | zh\$ | | |
| 17 | Spindle direction | spdir\$ | 1 0 -1 | Spindle forward Spindle stop Spindle reverse |
| 18 | (Not used) | | | |

W 1000 : Null tool change*Definition:* 1000

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

| | | | | |
|----|---------------------------|---------------------|---------------------------|--|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Cut pass | pass\$ | | |
| 5 | Condition code | cocode\$ | | |
| 6 | Offset number | offset\$ | | |
| 7 | (Not used) | | | |
| 8 | Initial wire taper | inittaper\$ | Positive 0 Negative | Taper, right No taper Taper, left |
| 9 | Feed rate | fr\$ | | |
| 10 | Flushing | water\$ | 0 1 2 | Off Flood Other |
| 11 | X thread position | threadx\$ | | |
| 12 | Y thread position | thready\$ | | |
| 13 | Z thread position | threadz\$ | | |
| 14 | X start position | startx\$ | | |
| 15 | Y start position | starty\$ | | |
| 16 | Z start position | startz\$ | | |
| 17 | Height of XY plane | xyheight\$ | | |
| 18 | Height of UV plane | uvheight\$ | | |
| 19 | X skewed wire thread | up_st_vecx\$ | | |
| 20 | Y skewed wire thread | up_st_vecy\$ | | |
| 21 | Z skewed wire thread | up_st_vecz\$ | | |
| 22 | Skewed wire thread | up_st_mode\$ | 0 1 2 3 | Off Apply to thread Apply to cut Apply to both thread/cut |

M R 1001 : Start-of-file tool change

Definition: 1001
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

| | | | | |
|----|-----------------------------|------------------|--|--|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Tool number | t\$ | | |
| 5 | Tool diameter offset number | tloffno\$ | | |
| 6 | Tool length offset number | tlingno\$ | | |
| 7 | Plane position | plane\$ | 0 XY plane 1 YZ plane 2 XZ plane | |
| 8 | Spindle speed in RPM | ss\$ | Positive Spindle forward 0 Spindle stop Negative Spindle reverse | |
| 9 | Feed rate | fr\$ | | |
| 10 | Coolant use | coolant\$ | 0 Off 1 Flood 2 Mist 3 Tool | |
| 11 | X rapid position | xr\$ | | |
| 12 | Y rapid position | yr\$ | | |
| 13 | Z rapid position | zr\$ | | |
| 14 | X home position | xh\$ | | |
| 15 | Y home position | yh\$ | | |
| 16 | Z home position | zh\$ | | |
| 17 | Axis substitution | rotaxis\$ | -2 Axis substitution, substitute Y, CCW -1 Axis substitution, substitute X, CCW 0 None 1 Axis substitution, substitute X, CW 2 Axis substitution, substitute Y, CW 11 Polar conversion, rotate about X 12 Polar conversion, rotate about Y 13 Polar conversion, rotate about Z 21 4-axis, rotate about X 22 4-axis, rotate about Y 23 4-axis, rotate about Z | |

| | | | |
|----|--------------------------------|-----------------|--|
| 18 | Diameter for axis substitution | rotdia\$ | |
|----|--------------------------------|-----------------|--|

L 1001 : Start-of-file tool change

Definition: 1001
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

| | | | | |
|----|-----------------------------|------------------|---------------------------|---|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Tool number | t\$ | | |
| 5 | Tool diameter offset number | tloffno\$ | | |
| 6 | Maximum spindle speed | maxss\$ | | |
| 7 | Tool orientation | orient\$ | | |
| 8 | Spindle speed | ss\$ | Positive 0 Negative | Spindle speed in RPM Spindle stop Spindle speed in surface units per minute |
| 9 | Feed rate | fr\$ | Positive Negative | Feed rate in units per minute Feed rate in units per revolution |
| 10 | Coolant use | coolant\$ | 0 1 2 3 | Off Flood Mist Tool |
| 11 | X rapid position | xr\$ | | |
| 12 | Y rapid position | yr\$ | | |
| 13 | Z rapid position | zr\$ | | |
| 14 | X home position | xh\$ | | |
| 15 | Y home position | yh\$ | | |
| 16 | Z home position | zh\$ | | |
| 17 | Spindle direction | spdir\$ | 1 0 -1 | Spindle forward Spindle stop Spindle reverse |
| 18 | (Not used) | | | |

W 1001 : Start-of-file tool change*Definition:* 1001

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

| | | | | |
|----|---------------------------|---------------------|---------------------------|--|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Cut pass | pass\$ | | |
| 5 | Condition code | cocode\$ | | |
| 6 | Offset number | offset\$ | | |
| 7 | (Not used) | | | |
| 8 | Initial wire taper | inittaper\$ | Positive 0 Negative | Taper, right No taper Taper, left |
| 9 | Feed rate | fr\$ | | |
| 10 | Flushing | water\$ | 0 1 2 | Off Flood Other |
| 11 | X thread position | threadx\$ | | |
| 12 | Y thread position | thready\$ | | |
| 13 | Z thread position | threadz\$ | | |
| 14 | X start position | startx\$ | | |
| 15 | Y start position | starty\$ | | |
| 16 | Z start position | startz\$ | | |
| 17 | Height of XY plane | xyheight\$ | | |
| 18 | Height of UV plane | uvheight\$ | | |
| 19 | X skewed wire thread | up_st_vecx\$ | | |
| 20 | Y skewed wire thread | up_st_vecy\$ | | |
| 21 | Z skewed wire thread | up_st_vecz\$ | | |
| 22 | Skewed wire thread | up_st_mode\$ | 0 1 2 3 | Off Apply to thread Apply to cut Apply to both thread/cut |

M R 1002 : Tool Change

Definition: 1002
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

| | | | | |
|----|-----------------------------|------------------|---|--|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Tool number | t\$ | | |
| 5 | Tool diameter offset number | tloffno\$ | | |
| 6 | Tool length offset number | tlngno\$ | | |
| 7 | Plane position | plane\$ | 0 1 2 | XY plane YZ plane XZ plane |
| 8 | Spindle speed in RPM | ss\$ | Positive 0 Negative | Spindle forward Spindle stop Spindle reverse |
| 9 | Feed rate | fr\$ | | |
| 10 | Coolant use | coolant\$ | 0 1 2 3 | Off Flood Mist Tool |
| 11 | X rapid position | xr\$ | | |
| 12 | Y rapid position | yr\$ | | |
| 13 | Z rapid position | zr\$ | | |
| 14 | X home position | xh\$ | | |
| 15 | Y home position | yh\$ | | |
| 16 | Z home position | zh\$ | | |
| 17 | Axis substitution | rotaxis\$ | -2 -1 0 1 2 11 12 13 21 22 23 | Axis substitution, substitute Y, CCW Axis substitution, substitute X, CCW None Axis substitution, substitute X, CW Axis substitution, substitute Y, CW Polar conversion, rotate about X Polar conversion, rotate about Y Polar conversion, rotate about Z 4-axis, rotate about X 4-axis, rotate about Y 4-axis, rotate about Z |

| | | | |
|----|--------------------------------|-----------------|--|
| 18 | Diameter for axis substitution | rotdia\$ | |
|----|--------------------------------|-----------------|--|

L 1002 : Tool Change

Definition: 1002
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18

| | | | | |
|----|-----------------------------|------------------|---------------------------|---|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Tool number | t\$ | | |
| 5 | Tool diameter offset number | tloffno\$ | | |
| 6 | Maximum spindle speed | maxss\$ | | |
| 7 | Tool orientation | orient\$ | | |
| 8 | Spindle speed | ss\$ | Positive 0 Negative | Spindle speed in RPM Spindle stop Spindle speed in surface units per minute |
| 9 | Feed rate | fr\$ | Positive Negative | Feed rate in units per minute Feed rate in units per revolution |
| 10 | Coolant use | coolant\$ | 0 1 2 3 | Off Flood Mist Tool |
| 11 | X rapid position | xr\$ | | |
| 12 | Y rapid position | yr\$ | | |
| 13 | Z rapid position | zr\$ | | |
| 14 | X home position | xh\$ | | |
| 15 | Y home position | yh\$ | | |
| 16 | Z home position | zh\$ | | |
| 17 | Spindle direction | spdir\$ | 1 0 -1 | Spindle forward Spindle stop Spindle reverse |
| 18 | (Not used) | | | |

W 1002 : Tool Change

Definition: 1002

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

| | | | | |
|----|---------------------------|---------------------|---------------------------|--|
| 1 | Program number | progno\$ | | |
| 2 | Starting sequence number | seqno\$ | | |
| 3 | Sequence number increment | seqinc\$ | | |
| 4 | Cut pass | pass\$ | | |
| 5 | Condition code | ccode\$ | | |
| 6 | Offset number | offset\$ | | |
| 7 | (Not used) | | | |
| 8 | Initial wire taper | inittaper\$ | Positive 0 Negative | Taper, right No taper Taper, left |
| 9 | Feed rate | fr\$ | | |
| 10 | Flushing | water\$ | 0 1 2 | Off Flood Other |
| 11 | X thread position | threadx\$ | | |
| 12 | Y thread position | thready\$ | | |
| 13 | Z thread position | threadz\$ | | |
| 14 | X start position | startx\$ | | |
| 15 | Y start position | starty\$ | | |
| 16 | Z start position | startz\$ | | |
| 17 | Height of XY plane | xyheight\$ | | |
| 18 | Height of UV plane | uvheight\$ | | |
| 19 | X skewed wire thread | up_st_vecx\$ | | |
| 20 | Y skewed wire thread | up_st_vecy\$ | | |
| 21 | Z skewed wire thread | up_st_vecz\$ | | |
| 22 | Skewed wire thread | up_st_mode\$ | 0 1 2 3 | Off Apply to thread Apply to cut Apply to both thread/cut |

M R 1003 : End of File

Definition: **1003**
 1 2 3

| | | | |
|---|-----------------|-------------|--|
| 1 | X home position | xh\$ | |
| 2 | Y home position | yh\$ | |
| 3 | Z home position | zh\$ | |

L 1003 : End of File

Definition: **1003**
 1 2 3

| | | | |
|---|-----------------|-------------|--|
| 1 | X home position | xh\$ | |
| 2 | (Not used) | | |
| 3 | Z home position | zh\$ | |

W 1003 : End of File

Definition: **1003**
 1 2 3

| | | | |
|---|-------------------|------------------|--|
| 1 | X thread position | threadx\$ | |
| 2 | Y thread position | thready\$ | |
| 3 | Z thread position | threadz\$ | |

L M R W 1004 : Cancel Cutter Compensation

Definition: **1004**
 [blank line]

Note: Even though Gcode 1004 has no parameters, a blank line must be output for the second line.

L M R W 1005 : Manual Entry / Insert text as comment

Definition: **1005**
 comment

| | |
|--|---|
| Text to be inserted into the NC program. | Text will be formatted as a comment and output immediately (before the current NC block). |
|--|---|

L M R W 1006 : Manual Entry / Insert text as code

Definition: **1006**
 comment

| | |
|--|--|
| Text to be inserted into the NC program. | Text will be inserted as NC code, not a comment, and output immediately (before the current NC block). |
|--|--|

L M R W 1007 : Manual Entry / Comment with move

Definition: **1007**
 comment

| | |
|---|--|
| Text to be inserted into the NC program | Text will be formatted as a comment and output with the next move. (See L M R W 1026 : Manual Entry / Comment as code, with move to format as code.) |
|---|--|

L M R W 1008 : Manual Entry / Tool operation comment

Definition: **1008**
 comment

| | |
|---|--|
| Text to be inserted into the NC program | |
|---|--|

W 1009 : Wire Cut Length (obsolete)

Definition: **1009**
 1 2 3

| | |
|---|--|
| 1 | Wirepath cut length cutlength\$ |
| 2 | (Not used) |
| 3 | (Not used) |

Note: This NCI Gcode is no longer output.

W 1010 : Wire Condition Change

Definition: **1010**
 1 2 3 4 5 6 7 8 9 1011 12 13 14

| | | | |
|----|-------------------|-------------------------|---|
| 1 | Wire compensation | cc\$ | 0 Cutter compensation modal (no change) 40 Cancel cutter compensation in the control 41 Cutter compensation in the control = left 42 Cutter compensation in the control = right 140 Cancel cutter compensation last move in the contour |
| 2 | Condition code | ccode\$ | |
| 3 | Wire offset | offset\$ | |
| 4 | Wire diameter | tldia\$ | |
| 5 | Register value 1 | reg1\$ | |
| 6 | Register value 2 | reg2\$ | |
| 7 | Register value 3 | reg3\$ | |
| 8 | Register value 4 | reg4\$ | |
| 9 | Register value 5 | reg5\$ | |
| 10 | Register value 6 | reg6\$ | |
| 11 | Register value 7 | reg7\$ | |
| 12 | Register value 8 | reg8\$ | |
| 13 | Register value 9 | reg9\$ | |
| 14 | Register value 10 | reg10\$ | |
| 15 | | ccode_epac_flg\$ | Indicates an approach point condition change. |

L M R W 1011 : Define Miscellaneous Reals

Definition: **1011**
 1 2 3 4 5 6 7 8 9 10

| | | | |
|----|-----------------------|---------------|--|
| 1 | Miscellaneous real 1 | mr1\$ | |
| 2 | Miscellaneous real 2 | mr2\$ | |
| 3 | Miscellaneous real 3 | mr3\$ | |
| 4 | Miscellaneous real 4 | mr4\$ | |
| 5 | Miscellaneous real 5 | mr5\$ | |
| 6 | Miscellaneous real 6 | mr6\$ | |
| 7 | Miscellaneous real 7 | mr7\$ | |
| 8 | Miscellaneous real 8 | mr8\$ | |
| 9 | Miscellaneous real 9 | mr9\$ | |
| 10 | Miscellaneous real 10 | mr10\$ | |

L M R W 1012 : Define Miscellaneous Integers

Definition: **1012**
 1 2 3 4 5 6 7 8 9 10

| | | | |
|----|--------------------------|---------------|--|
| 1 | Miscellaneous integer 1 | mi1\$ | |
| 2 | Miscellaneous integer 2 | mi2\$ | |
| 3 | Miscellaneous integer 3 | mi3\$ | |
| 4 | Miscellaneous integer 4 | mi4\$ | |
| 5 | Miscellaneous integer 5 | mi5\$ | |
| 6 | Miscellaneous integer 6 | mi6\$ | |
| 7 | Miscellaneous integer 7 | mi7\$ | |
| 8 | Miscellaneous integer 8 | mi8\$ | |
| 9 | Miscellaneous integer 9 | mi9\$ | |
| 10 | Miscellaneous integer 10 | mi10\$ | |

M R 1013 : Define Miscellaneous Parameters

Definition: 1013
1 2 3 4 5 6 7 8 9 10

| | | | | |
|---|---------------------------------------|------------------|-----|--|
| 1 | Cutter compensation use | cc\$ | 0 | Cutter compensation modal |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 2 | Tool diameter | tldia\$ | | |
| 3 | Tool corner radius | tcr\$ | | |
| 4 | Depth values to center or tip setting | cctotip\$ | 0 | Center |
| | | | 1 | Tip |
| 5 | View number | tplnno\$ | | The number of the view in Mastercam's view catalog. View numbers 1–8 correspond to Mastercam's standard system-defined views. If the view is a user-defined view, this will be a different, higher number. |
| | | | 0 | No matrix |
| | | | 1 | Top |
| | | | 2 | Front |
| | | | 3 | Back |
| | | | 4 | Bottom |
| | | | 5 | Right side |
| | | | 6 | Left side |
| | | | 7 | Isometric |
| | | | 8 | Axonometric |
| 6 | X coordinate of tool plane origin | tox\$ | | (relative to view) |
| 7 | Y coordinate of tool plane origin | toy\$ | | (relative to view) |
| 8 | Z coordinate of tool plane origin | toz\$ | | (relative to view) |
| 9 | Operation code | opcode\$ | 2 | Contour |
| | | | 3 | Drill |
| | | | 4 | Pocket |

| | | |
|----|-------------------------------|---|
| | | 5 Ruled |
| | | 6 2D swept |
| | | 7 3D swept |
| | | 8 Revolution |
| | | 9 Loft |
| | | 10 Coons |
| | | 13 Multisurface finish |
| | | 14 Multisurface rough |
| | | 15 Point |
| | | 16 Drill 5-axis |
| | | 17 Swarf 5-axis |
| | | 18 Curve 5-axis |
| | | 19 Facing |
| | | 20 5-axis multi-surface |
| | | 21 5-axis slice |
| | | 22 5-axis port |
| | | 23 5-axis circle |
| | | 25 Probe |
| 10 | Tool reference path and name* | strtoolpath+ strtool\$+ strtoolext |

L 1013 : Define Miscellaneous Parameters

Definition: 1013
1 2 3 4 5 6 7 8 9 10

| | | | | |
|----|-----------------------------------|---|-----|---|
| 1 | Cutter compensation | cc\$ | 0 | Cutter compensation modal |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 2 | Tool corner radius | tcr\$ | | Tool nose radius or tool radius of drill type tool |
| 3 | Tool diameter | tldia\$ | | Always 0 |
| 4 | (Not used) | | | |
| 5 | (Not used) | | | |
| 6 | X coordinate of tool plane origin | tox\$ | | (relative to view) |
| 7 | Y coordinate of tool plane origin | toy\$ | | (relative to view) |
| 8 | X coordinate of tool plane origin | toz\$ | | (relative to view) |
| 9 | Operation code | opcode\$ | 101 | Rough |
| | | | 102 | Finish |
| | | | 103 | Groove |
| | | | 104 | Thread |
| | | | 105 | Drill |
| | | | 106 | Point |
| 10 | Tool library path and name* | strtoolpath+ strtool\$+ strtoolext | | |

W 1013 : Define Miscellaneous Parameters

Definition: 1013
 1 2 3 4 5 6 7 8 9 10

| | | | | |
|----|-----------------------------|---|-----|--|
| 1 | Cutter compensation use | cc\$ | 0 | Cutter compensation modal |
| | | | 40 | Cancel cutter compensation in the control |
| | | | 41 | Cutter compensation in the control = left |
| | | | 42 | Cutter compensation in the control = right |
| | | | 140 | Cancel cutter compensation last move in the contour |
| 2 | Tool (wire) diameter | tldia\$ | | |
| 3 | Tool (wire) radius | ttrad\$ | | |
| 4 | Overburn amount | overburn\$ | | |
| 5 | Wire status | wire\$ | 0 | Off |
| | | | 1 | On |
| 6 | Power status | power\$ | 0 | Off |
| | | | 1 | On |
| 7 | Work origin X | wox\$ | | |
| 8 | Work origin y | woy\$ | | |
| 9 | Operation code | opcode\$ | 201 | 2D contour (no skim cuts, just single rough) |
| | | | 202 | 3D contour |
| | | | 203 | Canned (drill) |
| | | | 204 | No core (pocket) |
| | | | 205 | 4-axis taper, no skim |
| | | | 206 | 2D reverse skim cut |
| | | | 207 | (Not used) |
| | | | 208 | 4-axis direct, reverse skim cuts |
| | | | 209 | 4-axis direct, no skim cuts |
| | | | 210 | 4-axis taper, reverse skim cuts |
| | | | 211 | 4-axis taper, one-way skim cuts |
| | | | 212 | 4-axis direct, one-way skim cuts |
| | | | 213 | 2D one-way skim cuts |
| | | | 214 | Point operation (always rapid) |
| | | | 215 | 2-axis, one-way Agie collar skim cut |
| 10 | Power library path and name | strtoolpath+ strtool\$+ strtoolext | | Full 'path and name' of the power library used for the operation |

L M R W 1014 : Tool Plane View Matrix

Definition: 1014
1 2 3 4 5 6 7 8 9

| | |
|---|-------------|
| 1 | m1\$ |
| 2 | m2\$ |
| 3 | m3\$ |
| 4 | m4\$ |
| 5 | m5\$ |
| 6 | m6\$ |
| 7 | m7\$ |
| 8 | m8\$ |
| 9 | m9\$ |

| View | xx | xy | xz | yx | yy | yz | zx | zy | zz |
|-----------------|--------|---------|--------|---------|--------|--------|--------|---------|--------|
| Top (1) | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 |
| Front (2) | 1 | 0 | 0 | 0 | 0 | 1 | 0 | -1 | 0 |
| Back (3) | -1 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 |
| Bottom (4) | -1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | -1 |
| Right Side (5) | 0 | 1 | 0 | 0 | 0 | 1 | 1 | 0 | 0 |
| Left Side (6) | 0 | -1 | 0 | 0 | 0 | 1 | -1 | 0 | 0 |
| Isometric (7) | 0.7071 | 0.7071 | 0 | -0.4082 | 0.4082 | 0.8165 | 0.5774 | -0.5774 | 0.5773 |
| Axonometric (8) | 0.5 | -0.8536 | 0.1464 | 0.5 | 0.1464 | 0.8536 | 0.7071 | 0.5 | 0.5 |
| Variable Name | m1 | m2 | m3 | m4 | m5 | m6 | m7 | m8 | m9 |

W 1015 : Subroutine Parameters

Definition: 1015

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

| | | | |
|----|--------------------------|---------------------|---|
| 1 | Subroutine type settings | subtyp\$ | 0 Not a subroutine 1 Write subroutine 2 Call subroutine only |
| 2 | Subroutine number | subno\$ | |
| 3 | Thread/cut flag | td_ct_flg\$ | 0 No thread or cut 1 Allow thread the wire 2 Allow cut the wire |
| 4 | Tab cut | tabcut\$ | 0 No tab cut 1 Tab cut 2 Contour with tab cut |
| 5 | Wire trim | wtrim\$ | 0 Trim in control 1 Trim in computer 2 3D tracking |
| 6 | Skimcut options | skimpass\$ | 0 No skimcut +1 First skim cut pass on a contour -1 Subsequent skim cut pass on a contour -2 Last skim cut pass on a contour |
| 7 | Wire cut position X | cutx\$ | |
| 8 | Wire cut position Y | cuty\$ | |
| 9 | XY trimming plane | trimplane1\$ | |
| 10 | UV trimming plane | trimplane2\$ | |
| 11 | Register value 1 | reg1\$ | |
| 12 | Register value 2 | reg2\$ | |
| 13 | Register value 3 | reg3\$ | |
| 14 | Register value 4 | reg4\$ | |
| 15 | Register value 5 | reg5\$ | |
| 16 | Register value 6 | reg6\$ | |
| 17 | Register value 7 | reg7\$ | |
| 18 | Register value 8 | reg8\$ | |
| 19 | Register value 9 | reg9\$ | |
| 20 | Register value 10 | reg10\$ | |

M R L 1016 : Additional Miscellaneous Parameters

Definition: 1016
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

| | | | | |
|----|--|------------------------|---------------|--|
| 1 | Operation id | op_id\$ | | |
| 2 | Tool type | tool_typ\$ | | |
| 3 | Internal toolpath opcode | tool_op\$ | | (See tool_op\$ codes on page 70 for possible values.) |
| 4 | Construction view number | cplnno\$ | | |
| 5 | X coordinate of construction plane origin | corgx\$ | | (relative to view) |
| 6 | Y coordinate of construction plane origin | corgy\$ | | (relative to view) |
| 7 | Z coordinate of construction plane origin | corgz\$ | | (relative to view) |
| 8 | Cutter compensation in computer | cc_computer\$ | 0 41 42 | Off Left Right |
| 9 | Work offset number | workofs\$ | | |
| 10 | Metric is used | met_tool\$ | | |
| 11 | Number of flutes on cutter | n_flutes\$ | | |
| 12 | Active spindle for lathe | spindle_no\$ | | |
| 13 | Thread dimension | n_tap_thds\$ | | For a metric tap, mm per thread (pitch); for an inch tap, the number of threads per inch (this is the inverse of the pitch). |
| 14 | Station number (lathe) or head number (mill) | lstation\$ | | |
| 15 | Upper turret is used | lturret\$ | 0 1 | Lower turret Upper turret |
| 16 | Unique tool ID | ltool_id\$ | | |
| 17 | Transform operation ID | xform_op_id\$ | | If the current operation is the result of a transform operation, this is the op_id\$ of the transform operation. |
| 18 | Pitch (for tap tools) | tap_pitch\$ | | Output is in/thread or mm/thread, depending on part units. |
| 19 | Nesting operation ID | nesting_op_id\$ | | If the current operation is the result of a nesting operation, this is the op_id\$ of the nesting operation. |

W 1016 : Additional Miscellaneous Parameters

Definition: 1016
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

| | | | | |
|----|---------------------------------|------------------------|-----------------------|---|
| 1 | Operation id | op_id\$ | | |
| 2 | Finish spawned from Nocore | nocore_fin\$ | | |
| 3 | Internal toolpath opcode | tool_op\$ | | (See tool_op\$ codes on page 70 for possible values.) |
| 4 | Number of view used for Cplane | cplnno\$ | | (not used in Wire—always 0) |
| 5 | Cplane origin (X) | corgx\$ | | (not used in Wire—always 0) |
| 6 | Cplane origin (Y) | corgy\$ | | (not used in Wire—always 0) |
| 7 | Cplane origin (Z) | corgz\$ | | (not used in Wire—always 0) |
| 8 | Cutter compensation in computer | cc_computer\$ | 0 41 42 | Off Left Right |
| 9 | Work offset number | workofs\$ | | |
| 10 | Metric is used | met_tool\$ | | |
| 11 | Punch, die, open flag | pdo_type\$ | 0 1 2 | Punch Die Open |
| 12 | | spindle_no\$ | | (not used in Wire—always 0) |
| 13 | | rpd_hght\$ | | |
| 14 | | landheight\$ | | |
| 15 | Taper or slug type | contour_typ\$ | 0 1 2 3 4 | No taper Taper in Taper out Land up Land down |
| 16 | Chain height button selected | contour_pos\$ | 0 1 2 | XY height Land height UV height |
| 17 | | wox\$ | | Work plane origin (X) |
| 18 | | woy\$ | | Work plane origin (Y) |
| 19 | | woz\$ | | Work plane origin (Z) |
| 20 | Transform operation id | xform_op_id\$ | | If the operation is a transform operation, this is the operation ID of the transformed operation. |
| 21 | Nesting operation ID | nesting_op_id\$ | | If the current operation is the result of a nesting operation, this is the op_id\$ of the nesting operation. |

tool_op\$ codes

This table lists the **tool_op\$** codes output on the 1016 line:

Table 1: tool_op\$ codes

| Mill/ Router | Lathe | Wire | tool_op\$ | Operation |
|-----------------|-------|------|-----------|--------------------------------|
| M/R | | | 1 | Contour |
| M/R | | | 2 | Drill |
| M/R | | | 3 | Pocket |
| M/R | | | 4 | Transform operation |
| M/R | | | 5 | Multisurface rough parallel |
| M/R | | | 6 | Multisurface rough radial |
| M/R | | | 7 | Multisurface rough project |
| M/R | | | 8 | Multisurface rough flowline |
| M/R | | | 9 | Multisurface rough contour |
| M/R | | | 10 | Multisurface rough pocket |
| M/R | | | 11 | Multisurface finish parallel |
| M/R | | | 12 | Multisurface finish radial |
| M/R | | | 13 | Multisurface finish project |
| M/R | | | 14 | Multisurface finish flowline |
| M/R | | | 15 | Multisurface finish contour |
| M/R | | | 16 | For C-Hook- created operations |
| M/R | | | 17 | Manual entry |
| M/R | | | 18 | Circle mill |
| M/R | | | 19 | Point |
| M/R | | | 20 | Trimmed |
| M/R | | | 21 | Ruled |
| M/R | | | 22 | Revolved |
| M/R | | | 23 | Letters |
| M/R | | | 24 | Swept 2D |
| M/R | | | 25 | Swept 3D |
| M/R | | | 26 | Coons |
| M/R | | | 27 | Lofted |
| M/R | | | 28 | 5-axis drilling |
| M/R | | | 29 | 5-axis curve |
| M/R | | | 30 | Project toolpath onto a plane |

Table 1: tool_op\$ codes

| Mill/ Router | Lathe | Wire | tool_op\$ | Operation |
|-----------------|-------|------|-----------|--|
| M/R | | | 31 | Project toolpath onto a cylinder |
| M/R | | | 32 | Project toolpath onto a sphere |
| M/R | | | 33 | Project toolpath onto a cone |
| M/R | | | 34 | Project toolpath onto a cross section |
| M/R | | | 35 | Project toolpath onto a surface |
| M/R | | | 36 | Non-associative contour |
| M/R | | | 37 | Non-associative drilling |
| M/R | | | 38 | Non-associative pocketing |
| M/R | | | 39 | Multisurface finish pencil trace |
| M/R | | | 40 | Multisurface finish leftover stock |
| M/R | | | 41 | Multisurface finish steep |
| M/R | | | 42 | Multisurface finish shallow |
| M/R | | | 43 | Multisurface finish constant scallop |
| M/R | | | 44 | Multisurface rough plunge |
| M/R | | | 45 | Multisurface finish 5-axis flowline |
| M/R | | | 46 | Multisurface finish 4-axis |
| M/R | | | 47 | Merged in ASCII NCI |
| M/R | | | 48 | 5-axis swarf |
| M/R | | | 49 | 5-axis roll die |
| | L | | 51 | face contouring (C axis) |
| | L | | 52 | cross contouring (C axis) |
| | L | | 53 | C axis contouring |
| | L | | 55 | face drilling (C axis) |
| | L | | 56 | cross drilling (C axis) |
| | L | | 57 | C axis drilling |
| | L | | 60 | Rough |
| | L | | 61 | Finish |
| | L | | 62 | Grooving (note that chained grooves use 68.) |
| | L | | 63 | Threading |
| | L | | 64 | Drill |
| | L | | 65 | Point |
| | L | | 66 | Facing |

Table 1: tool_op\$ codes

| Mill/ Router | Lathe | Wire | tool_op\$ | Operation |
|-----------------|-------|------|-----------|---|
| | L | | 67 | Cutoff |
| | L | | 68 | Plunge rough; also, chained grooves |
| | L | | 69 | Manual entry |
| | L | | 70 | Merged in ASCII NCI |
| | L | | 71 | Lathe dynamic rough |
| | L | | 72 | Lathe contour rough |
| | | W | 74 | Contour |
| | | W | 75 | Canned |
| | | W | 76 | No Core |
| | | W | 77 | Manual entry |
| | | W | 78 | Point |
| | | W | 79 | 4-axis |
| | | W | 80 | Transform |
| | | W | 81 | Associative trimmed |
| | | W | 82 | Merged in ASCII NCI |
| | | W | 83 | Collar |
| M/R | | | 100 | Thread mill |
| M/R | | | 101 | Edit common operation parameters |
| M/R | | | 102 | Facing |
| M/R | | | 103 | Associative trimmed |
| M/R | | | 104 | Solid drill control operation |
| M/R | | | 105 | Slot mill |
| M/R | | | 106 | Helix bore |
| M/R | | | 107 | Multi-surface rough restmill |
| M/R | | | 108 | Associative nesting container operation |
| M/R | | | 109 | Multi-surface finish blend |
| M/R | | | 110 | Multi-surface 5axis, rough |
| M/R | | | 111 | Slice 5axis |
| M/R | | | 112 | Port 5axis |
| M/R | | | 113 | 5-axis circle |
| M/R | | | 130 | Tab cutoff |
| M/R | | | 131 | Multi-surface rough pocket, light |

Table 1: tool_op\$ codes

| Mill/ Router | Lathe | Wire | tool_op\$ | Operation |
|-----------------|-------|------|-----------|--|
| M/R | | | 132 | High-speed surface toolpaths |
| M/R | | | 133 | Nesting onionskin operation |
| M/R | | | 134 | 2-D hardmill machining/peel mill |
| R | | | 135 | Saw |
| M/R | | | 136 | FBM drill control operation |
| M/R | | | 137 | FBM mill pocket operation |
| M/R | | | 138 | FBM mill contour operation |
| M/R | | | 139 | Solid model operation |
| M/R | | | 150 | Probe cycle: probe motion |
| M/R | | | 151 | Probe cycle command block |
| M/R | | | 152 | Probe cycle header |
| M/R | | | 153 | Probe cycle trailer |
| M/R | | | 154 | SafetyZone linking operation |
| | L | | 201 | Canned finish |
| | L | | 202 | Canned rough |
| | L | | 203 | Canned rough and finish |
| | L | | 204 | Canned rough face |
| | L | | 205 | Canned rough and finish face |
| | L | | 206 | Canned pattern repeat rough |
| | L | | 207 | Canned pattern repeat rough and finish |
| | L | | 208 | Canned groove rough |
| | L | | 209 | Canned groove finish |
| | L | | 210 | Quick rough |
| | L | | 211 | Quick finish |
| | L | | 212 | Quick groove |
| | L | | 213 | C-hook generated |
| | L | | 214 | Stock transfer |
| | L | | 215 | Stock flip |
| | L | | 216 | Bar feed |
| | L | | 217 | Chuck clamp/unclamp |
| | L | | 218 | Tailstock operation |
| | L | | 219 | Steadyrest operation |

Table 1: tool_op\$ codes

| Mill/ Router | Lathe | Wire | tool_op\$ | Operation |
|-----------------|-------|------|-----------|--|
| | MT | | 220 | Pinch-turn operation |
| | L | | 221 | Custom operation with tool |
| | L | | 222 | Custom operation without tool |
| | L | | 223 | Custom operation reference |
| | L | | 224 | Plunge turn (chained geometry) |
| | L | | 225 | Plunge turn (point geometry) |
| | L | | 226 | Turret park operation |
| | MT | | 230 | Simple bar feed |
| | MT | | 231 | Bar feed with tool stop or tool pull |
| | MT | | 232 | Spindle clamp/unclamp |
| | MT | | 233 | Spindle advance/retract |
| | MT | | 234 | Spindle sync |
| | MT | | 235 | Tailstock advance/retract |
| | MT | | 236 | Turret park |
| R | | | 301 | Router contour (<i>obsolete</i>) |
| R | | | 302 | Router pocket (<i>obsolete</i>) |
| R | | | 303 | Router circmill (<i>obsolete</i>) |
| R | | | 304 | Router cutoff (<i>obsolete</i>) |
| R | | | 305 | Router surface rough pocket (<i>obsolete</i>) |
| R | | | 306 | Router multi-drill (block drill) |
| M/R | | | 416 | Engraving |
| Art | | | 439 | Art |
| M/R | | | 440 | Advanced multiaxis (Moduleworks) |

L M R 1017 : Construction Plane View Matrix

Definition: 1017
 1 2 3 4 5 6 7 8 9

| | | | |
|---|-------------------|--------------|--|
| 1 | X vector X in WCS | cm1\$ | |
| 2 | X vector Y in WCS | cm2\$ | |
| 3 | X vector Z in WCS | cm3\$ | |
| 4 | Y vector X in WCS | cm4\$ | |
| 5 | Y vector Y in WCS | cm5\$ | |
| 6 | Y vector Z in WCS | cm6\$ | |
| 7 | Z vector X in WCS | cm7\$ | |
| 8 | Z vector Y in WCS | cm8\$ | |
| 9 | Z vector Z in WCS | cm9\$ | |

L M R 1018 : Subprogram Start Definition

Definition: **1018**
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22
 23 24 25 26 27

| | | | | |
|----|-------------------------------------|---------------------------------------|---|--|
| 1 | Subprogram number | sub_op_id\$ / sub_ref_id\$ | | If this is a transform subprogram, this value is read into sub_ref_id\$. If this is a non-transform subprogram, this value is read into sub_op_id\$. Post writers who want to access the subprogram number should use main_prg_no\$ and sub_prg_no\$. |
| 2 | Actual operation id | sub_grp_id\$ | | |
| 3 | Transform / non-transform indicator | sub_trns_id\$ | 0 | Non-transform >0 Transform |
| 4 | Iteration counter | sub_sec_no\$ | | Transform operations: <0 = Off 0 = Original >0 = Copy Non-transform operations: <1 = Copy in transform 1 = Original >1 = Copy |
| 5 | Total number of instances (1-based) | sub_totl_no\$ | | |
| 6 | Chain # | sub_chn_no\$ | | For non-transform subprograms only |
| 7 | Absolute or incremental | sub_inc\$ | 0 | Absolute 1 Incremental |
| 8 | Transform type | sub_trnstyp\$ | 0 | Mirror 1 Rotate 2 Scale (not used) 3 Translate |
| 9 | | sub_trnmthd\$ | 0 | Translate method = Tool plane 1 Translate method = Tool plane with "Tool plane origin ONLY" checked 2 Translate method = Coordinate |
| 10 | Transform matrix | sub_m1\$ | | |
| 11 | Transform matrix | sub_m2\$ | | |
| 12 | Transform matrix | sub_m3\$ | | |
| 13 | Transform matrix | sub_m4\$ | | |
| 14 | Transform matrix | sub_m5\$ | | |
| 15 | Transform matrix | sub_m6\$ | | |
| 16 | Transform matrix | sub_m7\$ | | |

| | | | |
|----|--|----------------------|--|
| 17 | Transform matrix | sub_m8\$ | |
| 18 | Transform matrix | sub_m9\$ | |
| 19 | Transform X data | sub_trnsx\$ | Mirrored data: X-axis mirror. Set X-axis intersection. Rotated data: XYZ = center of rotation relative to current view. Translated data: XYZ = translation distance relative to original operation. |
| 20 | Transform Y data | sub_trnsy\$ | Mirrored data: Y-axis mirror. Set Y-axis intersection. Rotated data: XYZ = center of rotation relative to current view Translated data: XYZ = translation distance relative to original operation. |
| 21 | Transform Z data | sub_trnsz\$ | Rotated data: XYZ = center of rotation relative to current view Translated data: XYZ = translation distance relative to original operation |
| 22 | First tool in the transform group | sub_nxt_t\$ | |
| 23 | First head number in the transform group | sub_nxt_h\$ | |
| 24 | (for internal use only) | sub_nxt_tid\$ | |
| 25 | More than one tool in transform | sub_mny_t\$ | 0 Only one tool used in the transform 1 Multiple tools used in the transform |
| 26 | (for internal use only) | sub_nst_flg\$ | 1 Source 2 Source path 10 One level call 100 Separate subs 100 All Incremental 0 |
| 27 | (for internal use only) | | Flags if it is OK to write the 1018 line |

NCI file subprogram concepts

Mastercam writes subprogram information to the NCI file in long code format. All motion code is written as if subprograms weren't available. Subprogram information is written to the NCI file using the 1018 and 1019 NCI lines. These lines serve as a "wrapper" for the motion that is to become a subprogram. MP then reads these NCI lines and, based on the parameters in these lines, determines whether to:

- Write the initial subprogram.
- Make a call to the subprogram and call the appropriate predefined postblocks inside the post customization file (.PST).

Subprogram level hierarchy—Subprograms are designed to allow three levels of subprograms:

- The top level is the default NC level. This level is always active if no subs are defined.
- The second level is the transform level. This level is set for all transform subprograms.
- The third level is for all non-transform subprograms. In the absence of the transform level, third level subprograms are output at the second level.

1018 / 1019 position in the NCI file—The 1018 NCI line defines the start of a subprogram block and the 1019 NCI line defines the end of a subprogram block. For every 1018, there will be a corresponding 1019. The position of the 1018 and 1019 depend on whether the subprogram being written is a transform or non-transform subprogram.

- With transform subprograms—Transform subprograms position the 1018 directly after the 1020 NCI line. The 1019 NCI line then encloses all operations selected for the transform. This output and positioning continues for each transform location. Like parentheses, these NCI lines must nest any non-transform subprograms.
- With non-transform subprograms—Non-transform subprograms place the 1018 NCI line and 1019 NCI line dependent on the toolpath type.

A further distinction is made between Drill and Depth Cut subprograms:

- Non-transform depth cut subprograms—The 1018 NCI line is placed before the first position to be placed in the subprogram. The 1019 NCI line is placed after the last position to be placed in the subprogram.
- Non-transform drill subprograms—The 1018 NCI line is placed after the cycle definition (81 NCI line). The definition is outside of the subprogram so repeated points can be called with a different cycle definition. The 1019 NCI line is placed before the cancel drill cycle NCI line (80 NCI line).

Special Cases: Lathe turning canned cycles—The Lathe canned turning cycle(s) automatically produce a non-transform subprogram for the chain that was selected as the final profile. All motion from the first point in the chain to the last point in the chain is included in the subprogram. The numbering procedure used for any other non-transform subprogram applies and must be included when processing for subprograms. This subprogram is used internally by the MP language processor and doesn't follow the normal subprogram output method.

L M R 1019 : Subprogram End Definition

Definition: 1019
1 2 3 4 5 6

| | | | | |
|---|--------------------------------|---|---|--|
| 1 | Subprogram number | esub_op_id\$ / esub_ref_id\$ | | If param 3 (esub_trns_id\$) > 0, then: param 1 is read to esub_ref_id\$, esub_op_id\$ = 0 otherwise: param 1 is read to esub_op_id\$, esub_ref_id\$ = 0 Post writers who want to access the subprogram number should use main_prg_no\$ and sub_prg_no\$. |
| 2 | Actual operation id | esub_grp_id\$ | | |
| 3 | Transform / non-transform flag | esub_trns_id\$ | 0 | Non-transform >0 Transform |
| 4 | Iteration counter | esub_sec_no\$ | | Transform operations: <0 = Off 0 = Original >0 = Copy Non-transform operations: <1 = Copy in transform 1 = Original >1 = Copy |
| 5 | Total number of instances | esub_totl_no\$ | | |
| 6 | Chain # | esub_chn_no\$ | | For non-transform subprograms only |

The 1019 parameters are used to return the output stream level to the previous level that was set prior to 1018 being called. Therefore, 1018 and 1019 are matched pairs and only “non-transform” subprograms may nest in transform subprograms. The 1019 parameters match the first six parameters written on the matching 1018 line.

See **NCI file subprogram concepts** on page 77 more info about how this NCI line is used.

M R 1020 : Stock Parameters

Definition: 1020
1 2 3 4 5 6 7 8 9 10 11 12 13 14

| | | | |
|----|-------------------------------------|----------------------|---|
| 1 | X component, width | stck_ht\$ | |
| 2 | Y component, height | stck_wdth\$ | |
| 3 | Z component, thickness | stck_thck\$ | |
| 4 | X origin of block | stck_x\$ | |
| 5 | Y origin of block | stck_y\$ | |
| 6 | Z origin of block | stck_z\$ | |
| 7 | Origin corner | stck_cmr\$ | 0 Origin corner: top - center 1 Origin corner: top – upper left 2 Origin corner: top – upper right 3 Origin corner: top – lower right 4 Origin corner: top – lower left 5 Origin corner: bottom – upper left 6 Origin corner: bottom – upper right 7 Origin corner: bottom – lower right 8 Origin corner: bottom – lower left |
| 8 | Rotary axis in terms of Tplane | rotary_vecx\$ | |
| 9 | Rotary axis in terms of Tplane | rotary_vecy\$ | |
| 10 | Rotary axis in terms of Tplane | rotary_vecz\$ | |
| 11 | (Not used) | | |
| 12 | Force tool change? | force_tlchg\$ | State of Force tool change option on Tool parameters page. |
| 13 | Maximum spindle speed | maxss\$ | |
| 14 | String with the stock material name | stck_matl\$ | |

L 1020 : Stock Parameters

Definition: 1020
1 2 3 4 5 6 7 8 9 10 11 12 13 14

| | | | |
|----|--------------------------------|----------------------|--|
| 1 | Length of stock along Z axis | stck_ht\$ | |
| 2 | Maximum diameter of stock | stck_wdth\$ | |
| 3 | Same as 2 | stck_thck\$ | |
| 4 | Center of stock along Z axis | stck_x\$ | |
| 5 | Center of stock | stck_y\$ | |
| 6 | Center of stock | stck_z\$ | Always 0 |
| 7 | Origin corner | stck_cmr\$ | Always 0 |
| 8 | Rotary axis in terms of Tplane | rotary_vecx\$ | Always 0 |
| 9 | Rotary axis in terms of Tplane | rotary_vecy\$ | Always 0 |
| 10 | Rotary axis in terms of Tplane | rotary_vecz\$ | Always 0 |
| 11 | (Not used) | | |
| 12 | Force tool change? | force_tlchg\$ | State of Force tool change option on Tool parameters page. |
| 13 | Maximum spindle speed | maxss\$ | |
| 14 | Stock material name | stck_matl\$ | |

W 1020 : Stock Parameters

Definition: 1020
 1 2 3 4 5 6 7 8 9 10 11 12 13 14

| | | | |
|----|-------------------------------------|----------------------|---|
| 1 | X component, width | stck_ht\$ | |
| 2 | Y component, height | stck_wdth\$ | |
| 3 | Z component, thickness | stck_thck\$ | |
| 4 | X origin of block | stck_x\$ | |
| 5 | Y origin of block | stck_y\$ | |
| 6 | Z origin of block | stck_z\$ | |
| 7 | Origin corner | stck_cmr\$ | 0 Origin corner: top - center 1 Origin corner: top – upper left 2 Origin corner: top – upper right 3 Origin corner: top – lower right 4 Origin corner: top – lower left 5 Origin corner: bottom – upper left 6 Origin corner: bottom – upper right 7 Origin corner: bottom – lower right 8 Origin corner: bottom – lower left |
| 8 | (Not used) | | |
| 9 | (Not used) | | |
| 10 | (Not used) | | |
| 11 | Tank fill / empty flag | tank\$ | |
| 12 | | force_tlchg\$ | <i>(not used for Wire)</i> |
| 13 | (Not used) | | |
| 14 | String with the stock material name | stck_matl\$ | |

L M R W 1025 : Canned Text

Each parameter is a 4-digit number where:

- The first digit is the **cant_pos1\$–cant_pos20\$** value. This value ranges from 0–2 and indicates how the canned text is to be output:
 - ♦ 0 = output before the line
 - ♦ 1 = output with the line
 - ♦ 2 = output after the line
- The other three digits are the **cant_val1\$–cant_val20\$** value and indicate which canned text item to output.

Leading zeros are not output; so, for example, **0005** would be output simply as **5**.

Definition: **1025**
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

| 1 | Canned text parameter | cant_pos1\$+cant_val1\$ | Output mode + canned text ID |
|----|-----------------------|----------------------------------|------------------------------|
| 2 | | cant_pos2\$+cant_val2\$ | |
| 3 | | cant_pos3\$+cant_val3\$ | |
| 4 | | cant_pos4\$+cant_val4\$ | |
| 5 | | cant_pos5\$+cant_val5\$ | |
| 6 | | cant_pos6\$+cant_val6\$ | |
| 7 | | cant_pos7\$+cant_val7\$ | |
| 8 | | cant_pos8\$+cant_val8\$ | |
| 9 | | cant_pos9\$+cant_val9\$ | |
| 10 | | cant_pos10\$+cant_val10\$ | |
| 11 | | cant_pos11\$ cant_val11\$ | |
| 12 | | cant_pos12\$+cant_val12\$ | |
| 13 | | cant_pos13\$+cant_val13\$ | |
| 14 | | cant_pos14\$+cant_val14\$ | |
| 15 | | cant_pos15\$+cant_val15\$ | |
| 16 | | cant_pos16\$+cant_val16\$ | |
| 17 | | cant_pos17\$+cant_val17\$ | |
| 18 | | cant_pos18\$+cant_val18\$ | |
| 19 | | cant_pos19\$+cant_val19\$ | |
| 20 | | cant_pos20\$+cant_val20\$ | |

L M R W 1026 : Manual Entry / Comment as code, with move

Definition: **1026**
 comment

| | |
|---|---|
| Text to be inserted into the NC program | Text will be inserted directly as NC code (not formatted as a comment) and output with the next move. (See L M R W 1007 : Manual Entry / Comment with move to format as comment.) |
|---|---|

L M R W 1027 : Working Coordinate System

Definition: **1027**
 1 2 3 4 5 6 7 8 9 10 11 12

| | | |
|----|--------------------|--|
| 1 | t_wcs_m1\$ | |
| 2 | t_wcs_m2\$ | |
| 3 | t_wcs_m3\$ | |
| 4 | t_wcs_m4\$ | |
| 5 | t_wcs_m5\$ | |
| 6 | t_wcs_m6\$ | |
| 7 | t_wcs_m7\$ | |
| 8 | t_wcs_m8\$ | |
| 9 | t_wcs_m9\$ | |
| 10 | t_orgin_x\$ | |
| 11 | t_orgin_y\$ | |
| 12 | t_orgin_z\$ | |

M R 1028 : Head definition data

Definition: 1028
1 2 3 4 5 6 7 8 9 10 11 12

| | | | |
|----|----------------------|---|-----------------------|
| 1 | ra_type\$ | 0 | No special head (std) |
| | | 1 | Right-angle |
| | | 2 | Compound |
| | | 3 | Block drill |
| | | 4 | UST |
| 2 | ra_offset\$ | | |
| 3 | ra_vecx\$ | | |
| 4 | ra_vecy\$ | | |
| 5 | ra_vecz\$ | | |
| 6 | ra_svecx\$ | | |
| 7 | ra_svecy\$ | | |
| 8 | ra_svecz\$ | | |
| 9 | ra_block\$ | | |
| 10 | ra_station\$ | | |
| 11 | ra_head_grp\$ | | |
| 12 | ra_tc_type\$ | 0 | Auto T.C. (default) |
| | | 1 | Fixed unit |
| | | 2 | Manual T.C. |

M R 1029 : Head shift parameters

Definition: 1029
 1 2 3 4 5 6 7 8 9 10 11

| | | |
|----|-----------------|--|
| 1 | ra_hvecx\$ | |
| 2 | ra_hvecy\$ | |
| 3 | ra_hvecz\$ | |
| 4 | ra_bvecx\$ | |
| 5 | ra_bvecy\$ | |
| 6 | ra_bvecz\$ | |
| 7 | ra_tvecx\$ | |
| 8 | ra_tvecy\$ | |
| 9 | ra_tvecz\$ | |
| 10 | ra_translated\$ | |
| 11 | ra_rot_head\$ | |

L M R W 1031 Custom reals for transform operations

Definition: **1031**
 1 2 3 4 5 6 7 8 9 10

| | | | | |
|----|---|---------------------|--|--|
| 1 | Custom parameters (reals) for transform operation | trans_mr1\$ | | |
| 2 | | trans_mr2\$ | | |
| 3 | | trans_mr3\$ | | |
| 4 | | trans_mr4\$ | | |
| 5 | | trans_mr5\$ | | (not currently used— reserved for future use) |
| 6 | | trans_mr6\$ | | (not currently used— reserved for future use) |
| 7 | | trans_mr7\$ | | (not currently used— reserved for future use) |
| 8 | | trans_mr8\$ | | (not currently used— reserved for future use) |
| 9 | | trans_mr9\$ | | (not currently used— reserved for future use) |
| 10 | | trans_mr10\$ | | (not currently used— reserved for future use) |

L M R W 1032 Custom ints for transform operations

Definition: 1032
1 2 3 4 5 6 7 8 9 10

| | | | | |
|----|--|---------------------|--|--|
| 1 | Custom parameter (ints) for transform operation | trans_mi1\$ | | |
| 2 | | trans_mi2\$ | | |
| 3 | | trans_mi3\$ | | |
| 4 | | trans_mi4\$ | | |
| 5 | | trans_mi5\$ | | (not currently used— reserved for future use) |
| 6 | | trans_mi6\$ | | (not currently used— reserved for future use) |
| 7 | | trans_mi7\$ | | (not currently used— reserved for future use) |
| 8 | | trans_mi8\$ | | (not currently used— reserved for future use) |
| 9 | | trans_mi9\$ | | (not currently used— reserved for future use) |
| 10 | | trans_mi10\$ | | (not currently used— reserved for future use) |

M R 1042 : Begin probe operation/probe comments section

Definition: 1042
[blank line]

no parameters are output after the 1042—
only a blank line.

M R 1043 : End probe operation/probe comments section

Definition: 1043
[blank line]

no parameters are output after the 1043—
only a blank line.

L M R W 1050 : Define NCI Version Header

Definition: **1050**
 1 2 3 4 5 6 7 8 9

| | | | | |
|---|--------------------------------|--------------------|--|--|
| 1 | Mastercam major version number | vers_no\$ | | |
| 2 | [obsolete] | m_vers_no\$ | | |
| 3 | MCX file - day stamp | mc_day\$ | | |
| 4 | MCX file - month stamp | mc_mon\$ | | |
| 5 | MCX file - year stamp | mc_year\$ | | |
| 6 | MCX file - hour stamp | mc_hour\$ | | |
| 7 | MCX file - minute stamp | mc_min\$ | | |
| 8 | MCX file - second stamp | mc_sec\$ | | |
| 9 | MCX file name | smcname\$ | | |

L M R W 1051 : Machine name

Definition: **1051**
 string

| | |
|--|-----------------------------|
| Text to be inserted into the NC program. | Name of machine definition. |
|--|-----------------------------|

L M R W 1052 : Machine group comment

Definition: **1052**
 string

| | |
|--|---|
| Text to be inserted into the NC program. | Comment recorded in machine group properties. |
|--|---|

L M R W 1053 : Machine group name

Definition: **1053**
 string


| | |
|--|------------------------|
| Text to be inserted into the NC program. | Name of machine group. |
|--|------------------------|

L M R W 1054 : File descriptor

Definition: **1054**
 string

| | |
|--|---------------------------------------|
| Text to be inserted into the NC program. | Text of the file descriptor property. |
|--|---------------------------------------|

Note that in order for this to be output in your NCI file, the following option needs to be selected when posting:



Click the **Properties** button to edit the file descriptor.

M R 1056 : Probe data

Definition: **1056**
 string

| | |
|--|---|
| Text to be inserted into the NC program. | Renishaw probe data generated by the Productivity+ add-in. |
|--|---|

Control Flags Parameters

The control flags (also called “contour flags”) parameter is a single parameter passed from the NCI that carries several pieces of information in a single numeric value. The control flags parameter appears in every motion NCI line (Gcodes 0, 1, 2, 11, 81) to control such values as contour start, stop, and end, coolant, and 5-axis angles (for Mill) or rapid behavior (for Lathe).

Each decimal position in the control flags parameter value represents an individual flag. For example, 1 (first decimal place) is the contour stop flag, 10 (second decimal place) is the contour optional stop flag, 100 (third decimal place) is the contour end flag, and so forth. When added together, the result is a single number that represents multiple flags. Zero is implied when the place fields are empty, but only leading zeros may be omitted.

For example (in Mill), if:

```
cur_cflg$ = 201001
```

The control flags (reading left to right) set the following:

- Coolant flood
- Contour start on
- Contour optional stop off
- Contour stop on

The flag as read from the NCI is available as the predefined variable **cur_cflg\$**. You should rarely need to use the **cur_cflg\$** variable directly because the post executable sets separate variables for each flag.

The following tables describe the control flag settings for each product.

M R Mill / Router Control Flags Parameters

This is written to the NCI as a six-digit number. Each digit sets the value of a different pre-defined variable, as shown in this table. The entire six-digit number is stored in the **cur_cflg\$** variable.

| | | |
|------------------|--------|--|
| cstop\$ | 0 | Contour stop off |
| | 1 | Contour stop on |
| cgstop\$ | 00 | Contour optional stop off |
| | 10 | Contour optional stop on |
| cend\$ | 000 | Contour end off |
| | 100 | Contour end on |
| | 200 | Compensation OFF position |
| | 300 | Both contour and compensation off See notes below |
| cstart\$ | 0000 | Contour start off |
| | 1000 | Contour start on |
| | 2000 | Compensation ON position |
| | 3000 | Both contour & compensation start See notes below |
| rpd_typ\$ | 70000 | Pause for tool inspection (high speed surface toolpaths) |
| coolant\$ | 100000 | Coolant off |
| | 200000 | Coolant flood |
| | 300000 | Coolant mist |
| | 400000 | Coolant tool |

The Compensation ON/OFF position flag values are added to **cend\$** and **cstart\$** flag, if they exist at the same location in the NCI file. Example Contour END (100) and compensation OFF (200) can occur at the same location, so the flag values are added and you will see a value of 300.

The compensation flags (2000 and 200) are independent of the compensation actually being programmed in the toolpath program! They mark where compensation would normally be activated and canceled in the toolpath by Mastercam.

The raw values shown in this chart are not the values set in the individual variables. Example: if **cur_cflg\$** = **1000** (contour start), the variable **cstart\$** is set to 1.

L Lathe Control Flags Parameters

This is written to the NCI as a six-digit number. Each digit sets the value of a different pre-defined variable, as shown in this table. The entire six-digit number is stored in the **cur_cflg\$** variable.

| | | |
|------------------|--------|--|
| cstop\$ | 0 | Contour stop off |
| | 1 | Contour stop on |
| cgstop\$ | 00 | Contour optional stop off |
| | 10 | Contour optional stop on |
| cend\$ | 000 | Contour end off |
| | 100 | Contour end on |
| | 200 | Compensation OFF position |
| | 300 | Both contour and compensation off See notes below |
| cstart\$ | 0000 | Contour start off |
| | 1000 | Contour start on |
| | 2000 | Compensation ON position |
| | 3000 | Both contour & compensation start See notes below |
| rpd_typ\$ | 10000 | Clear to home |
| | 20000 | Rapid to start |
| | 30000 | Rapid around obstruction |
| | 40000 | Rapid between points |
| | 50000 | Entry / Exit |
| | 60000 | Start / End rough turning cycles |
| | 70000 | Pause for tool inspection (groove toolpaths) |
| coolant\$ | 100000 | Coolant off |
| | 200000 | Coolant flood |
| | 300000 | Coolant mist |
| | 400000 | Coolant tool |

The Compensation ON/OFF position flag values are added to **cend\$** and **cstart\$** flag, if they exist at the same location in the NCI file. Example: Contour END (100) and compensation OFF (200) can occur at the same location, so the flag values are added and you will see a value of 300.

The compensation flags (2000 and 200) are independent of the compensation actually being programmed in the toolpath program! They mark where compensation would normally be activated and canceled in the toolpath by Mastercam.

The raw values shown in this chart are not the values set in the individual variables. Example: if **cur_cflg\$** = **1000** (contour start), the variable **cstart\$** is set to 1.

W Wire Control Flags Parameters

This is written to the NCI as a nine-digit number. Each digit sets the value of a different pre-defined variable, as shown in this table. The entire nine-digit number is stored in the **cur_cflg\$** variable.

| | | |
|-------------------|-----------|--|
| cstop\$ | 0 | Contour stop off |
| | 1 | Contour stop on |
| cgstop\$ | 00 | Contour optional stop off |
| | 10 | Contour optional stop on |
| cend\$ | 000 | Contour end off |
| | 100 | Contour end on |
| | 200 | Compensation OFF position |
| | 300 | Both contour and compensation off |
| | | See notes below |
| cstart\$ | 0000 | Contour start off |
| | 1000 | Contour start on |
| | 2000 | Compensation ON position |
| | 3000 | Both contour & compensation start |
| | | See notes below |
| thrd_cut\$ | 10000 | Thread the wire |
| | 20000 | Cut the wire |
| water\$ | 100000 | Water off |
| | 200000 | Water on |
| | 300000 | Water option 1 |
| power\$ | 1000000 | Power off |
| | 2000000 | Power on |
| tank\$ | 10000000 | Tank empty |
| | 20000000 | Tank fill |
| epac_flg\$ | 100000000 | Indicates that the current move is an approach point that has been added. This typically occurs if the power (epac) settings are programmed to change after the approach move. |

The Compensation ON/OFF position flag values are added to **cend\$** and **cstart\$** flag, if they exist at the same location in the NCI file. Example: Contour END (100) and compensation OFF (200) can occur at the same location, so the flag values are added and you will see a value of 300.

The compensation flags (2000 and 200) are independent of the compensation actually being programmed in the wirepath! They mark where compensation would normally be activated and canceled in the wirepath by Mastercam.

The raw values shown in this chart are not the values set in the individual variables. Example: if **cur_cflg\$** = 1000 (contour start), the variable **cstart\$** is set to 1.

Tool information (20000s parameters)

Tool information lines are added in the 20000s lines in the NCI file. The data is presented in a two-line format:

- The first line contains the parameter number.
- The second line contains the value or values.

The second line can be interpreted as either a single string or as a series of numeric values separated by spaces. In the reference sections that follow, for each parameter there is a prototype that describes the data structure of the parameter value, followed a description of the actual values. These are not assigned variable names but can be scanned for the desired values with the function **rpar**.

```
g
string
```

Note that some codes might be output with a blank line if that value is not used or is otherwise not meaningful for a specific product.

The codes are divided into four sections:

- The first section contains codes numbered below 20100 and above 20500. They are either Mill/Router-specific, or are used across multiple products.
- The second section contains Lathe-specific codes, numbered from 20100–20199.
- The third section contains Wire-specific codes. Most of these are numbered above 20200.
- The fourth section describes the parameters that are used to create custom interfaces for Wire machines. These are numbered above 22000.

See **NCI Gcodes** for information about NCI Gcodes numbered from 0–1056.

See the *Working with Parameters Application Guide* to learn more about how to access these values in your post.

Mill/Router/Generic

20001 : Tool name

Used in: **Mill Lathe Router**

Definition: 20001
string (tool name)

20002 : Manufacturer's tool code

Used in: **Mill Lathe Router**

Definition: 20002
string (manufacturer's tool code)

20003 : Chuck name

Used in: **Mill Router**

Definition: 20003
string (chuck name)

| General | |
|---------------------------|--------------------------------------|
| Name: | 20001 3/8 BULL ENDMILL 0.0625 |
| Description: | n/a |
| Manufacturer name: | n/a |
| Manufacturer's tool code: | 20002 |
| Required pilot diameter: | 20007.1 0 |
| ^ | |
| Helix Angle: | 0 n/a |
| Helix Type: | Up n/a |
| Chuck: | 20003 |

20004 : Tool definition parameters I




Used in: **Mill Router**

Definition: **20004**

**1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22
23 24 25 26 27**

- 1 | Tool number
- 2 | Tool type:
 - 0 = Custom
 - 1 = Center drill
 - 2 = Spot drill
 - 3 = Drill
 - 4 = Right-hand tap
 - 5 = Left-hand tap
 - 6 = Reamer
 - 7 = Boring bar
 - 8 = Counterbore
 - 9 = Countersink
 - 10 = End mill (flat)
 - 11 = Ball mill
 - 12 = Chamfer mill

▾ Milling

| | | |
|---|--|--|
|  End Mill 10 |  Bull Mill 19 |  Ball Mill 11 |
|  Face Mill 13 |  Radius Mill 15 |  Chamfer Mill 12 |
|  Slot Mill 14 |  Taper Mill 17 |  Dove Mill 16 |
|  Lollipop Mill 18 |  Engrave Tool 21 |  Thread Mill 24 |
|  Barrel Mill 25 |  Custom Tool 0 | |

▾ Holemaking


| | | |
|---|---|---|
|  Drill 3 |  Spot Drill 2 |  Center Drill 1 |
|  Reamer 6 |  Countersink 9 |  Counterbore 8 |
|  Tap 4 (RH), 5 (LH) |  Bradpoint Drill 22 |  Bore Bar 7 |
|  Custom Tool 0 | not shown: Block drill = 20 | |

| | |
|----|---|
| | 13 = Face mill |
| | 14 = Slot mill |
| | 15 = Radius mill |
| | 16 = Dove mill |
| | 17 = Taper mill |
| | 18 = Lollipop mill |
| | 19 = Bull mill |
| | 20 = Block drill |
| | 21 = Engrave tool |
| | 22 = Bradpoint drill |
| | 23 = <i>future use</i> |
| | 24 = Thread mill |
| | 25 = Barrel mill |
| 3 | Tool material: |
| | 1 = High-speed steel (HSS) |
| | 2 = Carbide |
| | 3 = Coated carbide (Ti coated) |
| | 4 = Ceramic |
| | 5 = User defined 1 |
| | 6 = User defined 1 |
| 4 | Corner radius type: |
| | 0 = Flat mill |
| | 1 = Bullnose mill |
| | 2 = Spherical mill |
| 5 | Tool diameter |
| 6 | Corner radius |
| 7 | Number of threads/inch or pitch (mm) |
| 8 | Tool tip included angle |
| 9 | Diameter offset register # |
| 10 | Length offset register # |
| 11 | Linear feed rate |
| 12 | Plunge feed rate |
| 13 | Retract feed rate |
| 14 | Spindle speed |
| 15 | Coolant type (<i>obsolete</i>) |
| 16 | Number of flutes |
| 17 | Shoulder or shank diameter |
| 18 | Taper length |
| 19 | Chamfer length (tip chamfer) |
| 20 | Drill length (pilot length) for center or counter-bore drill |
| 21 | Drill diameter (pilot diameter) for center or counter-bore drill |
| 22 | Secondary radius: upper corner radius for slot mills, profile radius for barrel mills |

- 23 Secondary chamfer length: upper corner chamfer for slot mills
- 24 Secondary chamfer angle: upper corner angle for slot mills
- 25 Shank type: 0 = straight, 1 = tapered, 2 = reduced neck:



- 26 Neck diameter for reduced neck shanks
- 27 Thread form for thread mill tool:



20005 : Cutting parameters (drills)

Used in: **Mill Router**

Definition: **20005**
1 2 3 4 5 6 7 8 9

- 1 Canned cycle type
- 2 1st peck increment (% of tool diameter)
- 3 2nd peck increment (% of tool diameter)
- 4 Peck clearance (% of tool diameter)
- 5 Chip break (% of tool diameter)
- 6 Dwell in seconds
- 7 Tip angle
- 8 Thread root diameter
- 9 Shift value off wall for fine boring (% of tool diameter)—for boring tools only.


20006 : Cutting parameters (mills)*Used in:* **Mill Router***Definition:* **20006**
1 2 3 4 5 6 7 8 9

- | | |
|---|---|
| 1 | Type of operation: 0 = Rough tool and Finish tool 1 = Rough tool only 2 = Finish tool only |
| 2 | % of tool diameter for rough stepover (XY) |
| 3 | % of tool diameter for rough stepover (Z) |
| 4 | % of tool diameter for finish stepover (XY) |
| 5 | % of tool diameter for finish stepover (Z) |
| 6 | Tip diameter for a chamfer mill, or secondary diameter for a face mill. |
| 7 | Thread root diameter |
| 8 | <i>(Obsolete)</i> |
| 9 | <i>(Future use)</i> |

20007 : Tool definition parameters II*Used in:* **Mill Router***Definition:* **20007**
1 2 3 4 5 6 7 8 9 10 11 12 13

- | | |
|---|---|
| 1 | Required pilot diameter (minimum diameter required for tool to plunge) |
| 2 | Cutting length / flute length |
| 3 | Overall length |
| 4 | Shoulder length |
| 5 | Arbor diameter |
| 6 | Holder diameter <i>(for X6 and earlier tool definitions— deprecated for X7 and later)</i> |

- 7 | Holder length (for X6 and earlier tool definitions—
depreciated for X7 and later)
Parameters 6 and 7 were originally used for the holder diameter and holder length in “legacy” tool definitions—meaning tools that were created in Mastercam versions X6 and earlier. Tool holders that have been created with the newer tool holder definition functions in Mastercam X7 and later do not use these parameters.
These parameters are maintained only for compatibility with older tools. If a tool definition in your part was originally created in X6 or earlier, parameters 6 and 7 will continue to be output with the original values. Otherwise, do not use them.
- 8 | Spindle direction: 0 = CW, 1 = CCW
- 9 | % of surface ft/min to be applied against workpiece material sfm
- 10 | % of feed/tooth to be applied against workpiece material fpt
- 11 | Units for: 0 = values in inches, 1 = metric
- 12 | The **Tool Projection** distance from the **Holder** page. For pre-X8 operations, this value will not be output until the toolpath has been regenerated in X8.
- 13 | Total holder length.
For pre-X8 operations, this value will not be output until the toolpath has been regenerated in X8.



20008 : Aggregate head parameters*Used in:* **Mill Router***Definition:* **20008**
1 2 3 4 5 6 7 8 9

| | |
|---|---|
| 1 | head axis in X |
| 2 | head axis in Y |
| 3 | head axis in Z |
| 4 | head body type: (0 = cylinder, 1 = square) |
| 5 | head body diameter |
| 6 | head body length |
| 7 | station body type (0 = cylinder, 1 = square) |
| 8 | station body diameter |
| 9 | station body length |

20009 : Custom tool geometry*Used in:* **Mill Router***Definition:* **20009**
1 2

| | |
|---|--|
| 1 | The level on which custom tool geometry is stored. |
| 2 | The source of the custom geometry (0=auto, 1=file, 2=level). |

20010 : Construction plane name*Used in:* **Mill Lathe Router Wire***Definition:* **g = 20010**
string (construction plane name)**20011 : Construction plane comment***Used in:* **Mill Lathe Router Wire***Definition:* **20011**
string (construction plane comment)

This line has no value in Wire. It will be output, but will always be blank.

20012 : Tool plane name

Used in: **Mill Lathe Router Wire**

Definition: **20012**
 string (tool plane name)

20013 : Tool plane comment

Used in: **Mill Lathe Router Wire**

Definition: **20013**
 string (tool insert name)

This line has no value in Wire. It will be output, but will always be blank.

20014 : WCS plane name

Used in: **Mill Lathe Router Wire**

Definition: **20014**
 string (WCS plane name)

20015 : WCS plane comment

Used in: **Mill Lathe Router Wire**

Definition: **20015**
 string (WCS plane comment)

This line has no value in Wire. It will be output, but will always be blank.

20016 : Material name

Used in: **Mill Lathe Router**

Definition: **20016**
 string (material name)

This line has no value in Wire. It will be output, but will always be blank.

20017 : Material comment

Used in: **Mill Lathe Router**

Definition: **20017**
 string (material comment)

This line has no value in Wire. It will be output, but will always be blank.

20018 : Machine group name

Used in: **Mill Lathe Router Wire**

Definition: **20018**
string (machine group name)

20501 : Nested sheet material name

Used in: **Mill Router**

Definition: **20501**
string (material name)

Sheet information is output for each sheet change notification in the NCI.

20502 : Nested sheet parameters

Used in: **Mill Router**

Definition: **20502**
1 2 3 4 5 6 7 8 9 10 11 12

Sheet information is output for each sheet change notification in the NCI.

| | |
|----|---|
| 1 | sheet length (X dimension) |
| 2 | sheet width (Y dimension) |
| 3 | Sheet thickness (temporary placeholder) |
| 4 | sheet corner (1 = lower left, 2 = lower right, 3 = upper right, 4 = upper left) |
| 5 | sheet number |
| 6 | sheet instance |
| 7 | integer pad |
| 8 | integer pad |
| 9 | integer pad |
| 10 | real pad |
| 11 | real pad |
| 12 | real pad |

20600 : Axis combination components

Used in: **Mill Router Lathe Wire**

Definition: **20600**
1 2 3 4 5

A 20600 line is output for each component in the axis combination.

| | |
|---|--------------------------|
| 1 | Entity ID for component |
| 2 | String ID for component |
| 3 | Axis label (absolute) |
| 4 | Axis label (incremental) |
| 5 | Component name |

20601 : Axis combination info

Used in: **Mill Router Lathe Wire**

Definition: **20601**
 1 2 3 4

A 20601 line is output for the axis combination itself.

| | | |
|---|--|--|
| 1 | | Entity ID |
| 2 | | String ID |
| 3 | | 1=Mapped axis combination, otherwise 0 |
| 4 | | Axis combination name |

20700 : Tool change info per data stream


This is no longer written to the NCI, beginning with Mastercam X7.

20800 : Tool diameter for multiaxis comp in control

Used in: **Mill Router Lathe**

Definition: **20800**
 0

This parameter captures the tool diameter from the **Cut Pattern** page.



This is output for all operations except lathe misc ops. It will be output for tool changes and for null tool changes where the operation changes. It will be output following the 20009 line for mill tool changes, and the 20112 line for lathe tool changes.

If the operation is not a multiaxis operation, the value will be zero.

Lathe

20100 : Lathe tool programming parameters

Used in: **Lathe**

Definition: **20100**
1 2 3 4 5 6 7 8 9

| | |
|---|---|
| 1 | tool slot number |
| 2 | tool type: 0=General Turning Tools 1=Threading Tools 2=Grooving/Parting Tools 3=Boring Bars 4=Drills, Taps, Reamers 5=Custom Geometry Tools |
| 3 | use in top turret |
| 4 | active spindle |
| 5 | tool angle in turret (in degrees) |
| 6 | top turret |
| 7 | tool number |
| 8 | tool offsets for right edge |
| 9 | tool offsets for left edge |

20101 : Lathe tool cutting parameters

Used in: **Lathe**

Definition: **20101**
1 2 3 4 5 6 7 8 9 10 11

| | |
|----|---|
| 1 | Default Feed rate |
| 2 | Type of default Feed rate : 82 = R (in/mm per rev), 77 = M (inch/mm per minute) |
| 3 | Default Plunge rate |
| 4 | Default Spindle speed |
| 5 | Units for default Spindle speed : 0 = RPM, 1 = CSS |
| 6 | Value in % of Material CS field |
| 7 | Value in % of Material Feed/rev field |
| 8 | Spindle direction |
| 9 | Default Coolant options. This value is bit-mask whose value is hex represents the on/off state and start point option for each coolant option. |
| 10 | 1 = Metric values option selected, 0 = inch values |

11 | Type of default **Plunge rate**: 82 = in (mm)/rev, 77 = inch (mm)/min.

Type - General Turning | Inserts | Holders | Parameters

Program Parameters

Tool number: 12 Tool station number: 12
 Tool offset number: 12 Tool back offset number: 1



Default Cutting Parameters

Feed rate: 0.01 20101.1 in/rev in/min 20101.2
 Plunge rate: 0.005 20101.3 in/rev in/min 20101.11 20101.9
 % of Material Feed/Rev: 100.0 20101.7 Coolant...
 Spindle speed: 200 20101.4 CSS RPM 20101.5
 % of Material CS: 100.0 20101.6 Compute From Material...

Toolpath Parameters

Amount of cut (rough): 0.1 Retraction amount (face): 0.0
 Amount of cut (finish): 0.0 X overcut amount (face): 0.0
 Overlap amount (rough): 0.01

Compensation

  Tool Clearance... 20101.10 Metric values

Tool name: OD 55 deg Right
 Manufacturer's tool code:

20102 : Lathe tool geometry

Used in: **Lathe**

Definition: **20102**
 1 2 3 4 5 6 7 8

- 1 | tool orientation
- 2 | tool clearance angle for programming
- 3 | tool rake angle for programming
- 4 | tool width for programming
- 5 | tool height for programming
- 6 | tool center for programming
- 7 | tool center for programming
- 8 | comp to center of insert nose radius

20103 : Insert name

Used in: **Lathe**


Definition: **20103**
string (tool insert name)

20104 : Insert parameters


Used in: **Lathe**

Definition: **20104**
1 2 3 4 5 6 7 8

1 ASCII code for the insert **Shape**. For general turning and boring tools:




For grooving tools:



- 2 IC diameter
- 3 length
- 4 corner radius
- 5 thickness
- 6 insert material for feed speed calculations
- 7 insert type (-1 = not used)
- 8 is insert defined in mm or inches?

20105 : Insert parameters, general turning/boring*Used in:* **Lathe***Definition:* **20105**
1 2 3 4 5 6 7

1 | The ASCII code of the letter for the selected **Cross Section** type.



2 | end relief angle
 3 | roughing depth of cut
 4 | finish depth of cut
 5 | roughing overlap amount
 6 | facing retraction amount
 7 | facing x overcut amount

20106 : Insert parameters, threading*Used in:* **Lathe***Definition:* **20106**
1 2 3 4 5 6 7 8 9 10 11 12

1 | insert style: 1 = top notch, 2 = lay down
 2 | insert type:
 1 = Unified type 1
 2 = Unified type 2
 3 = Metric type 1
 4 = Metric type 2
 5 = Acme
 6 = Acme stub
 7 = Buttress
 3 | insert for external thread?
 4 | design thread pitch
 5 | top notch dist. to insert point from side of insert
 6 | laydown height of insert (~= thread depth)
 7 | width of flat for ACME, buttress

| | |
|----|-----------------------|
| 8 | depth of 1st cut |
| 9 | depth of last cut |
| 10 | finish pass allowance |
| 11 | anticipated pull-off |
| 12 | number of spring cuts |

20107 : Insert parameters, grooving/parting*Used in:* **Lathe***Definition:* **20107**
1 2 3 4 5 6 7 8 9 10

| | |
|----|---|
| 1 | cutting length of insert |
| 2 | shank width |
| 3 | end length for top notch type P |
| 4 | distance to insert point for top notch type V |
| 5 | end angle for Sandvik type 5R |
| 6 | roughing depth of cut |
| 7 | finish depth of cut |
| 8 | stock clearance |
| 9 | backoff percent |
| 10 | roughing overlap amount |

20108 : Drill tool parameters*Used in:* **Lathe***Definition:* **20108**
1 2 3 4 5 6 7 8 9 10 11 12 13 14

| | |
|---|--|
| 1 | drill, tap, reamer, etc: 1=Drill 2=Center Drill 3=Countersink 4=Counterbore 5=End Mill 6=Reamer 7=Right Hand Tap 8=Left Hand Tap |
| 2 | tool diameter |
| 3 | shank diameter |
| 4 | tip included angle |
| 5 | flute length |
| 6 | length at cutting diameter |
| 7 | flute helix angle |
| 8 | number of flutes |

| | |
|----|---|
| 9 | chamfer height for reamers, taps |
| 10 | tip diameter for center drills |
| 11 | tip length for center drills |
| 12 | shoulder angle for center drills |
| 13 | thread pitch for taps |
| 14 | tap type: 1=Tapered Tap 2=Plug Tap 3=Bottoming Tap |

20109 : Drilling parameters*Used in:* **Lathe***Definition:* **20109
1 2 3 4 5 6**

| | |
|---|---------------------------|
| 1 | preferred drilling cycle |
| 2 | 1st peck increment |
| 3 | subsequent peck increment |
| 4 | peck clearance |
| 5 | retraction amount |
| 6 | dwel time |

20110 : Holder name*Used in:* **Lathe***Definition:* **20110
string (tool holder name)**


20111 : Holder parameters

Used in: **Lathe**

Definition: **20111**

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15


1 The ASCII code of the letter that identifies the selected holder **Style**. For general turning tools and boring bars, the code matches the picture in the dialog box (65 = A, 82=R, etc.).




For grooving and threading codes, see the charts following this table.

- 2 qualified length
- 3 maximum width
- 4 shank width
- 5 shank height
- 6 'head' length
- 7 'head' width
- 8 corner chamfer width
- 9 corner chamfer height
- 10 end cutting edge angle
- 11 side cutting edge angle
- 12 True = round shank
- 13 left hand tool?
- 14 vertically mounted tool?
- 15 is holder defined in mm or inches?

Grooving tools use the following holder style codes:



Threading tools use the following holder style codes:



20112 : Custom tool geometry file name

Used in: **Lathe**

Definition: **20112**
 string (custom tool geometry file name)

29999 : Tool inspection comment

Note that this line is not output before the tool change, like the other 20000s lines—instead, it is output in the toolpath at the point where the tool inspection occurs. See the MP Application Guide, *Working with tool and operation parameters*, to learn more.

Used in: **Lathe**

Definition: **29999**
 string (lathe tool inspection comment)

Wire

20019 : Pass comment from power library

Used in: **Wire**

Definition: **20019**
 string (power library pass comment)

This line has a value in Wire only. It is output for Mill and Router toolpaths, but will be blank.

20200 : Wirepath stock to leave

Used in: **Wire**

Definition: **20200**
 1 2 3 4 5 6 7

| | | | |
|---|-----------------------|---|---|
| 1 | stock_leave\$ | | |
| 2 | offset_total\$ | | Radius + overburn + stock-to-leave amount. |
| 3 | offset_mach\$ | 0 | Program coordinates; the coordinates in the NCI are already shifted by the stock-to-leave amount. |
| | | 1 | Machine offset register; the stock-to-leave offset is done at the control. |
| 4 | tlrad\$ | | Radius of the wire. |
| 5 | overburn\$ | | |
| 6 | cc_type\$ | 0 | Computer |
| | | 1 | Control |
| | | 2 | Both |
| | | 3 | Reverse both |
| | | 4 | Off |
| 7 | offset\$ | | Offset register number |

The 20200 line is unique in that its parameters are assigned to pre-defined variables and can be accessed directly, without needing to use the standard parameter read functions. To enable this functionality, the **listrad\$** switch needs to be set to 2. When **listrad\$** is *not* set to 2, **tlrad\$** and **offset\$** are read from the tool change and 1010 lines. When **listrad\$** is set to 2, the values from the tool change and 1010 lines are ignored. Note that **bidnxtool\$** must also be set to 1.

Parameters for custom interfaces

Mastercam X4 introduced a new range of parameters numbered 22xxx. These are designed to support custom interfaces, principally for Wire. The new 22xxx parameters are designed to encapsulate settings from the new interfaces and pass them to the post. These are then read and stored during **pparameter\$** like any other 20000-style parameters

- The first custom interface was the Agievision interface, introduced in Mastercam X4.
- The second custom interface was the TECH library interface for Makino and Mitsubishi machines, introduced in Mastercam X5.

The new interfaces use the following numbering scheme:

- Parameter numbers 22001–22050 will be used for generic parameters. These numbers will not be unique and will be reused in multiple interfaces. See **Common parameters** on page 117.
- Parameters numbered from 22051–22100 are used by the Agievision interface. See **Agievision parameters** on page 121.
- Parameters numbered from 22101–22150 are used by the TECH library interface. See **TECH library parameters** on page 141.

Future interfaces will be assigned new parameter numbers in blocks of 50.

Common parameters

22001 : Machine model

Used in: **Wire (custom interfaces)**

Definition: **22001**
 string (machine model)

From control definition. See **Control definition: Control Model page** on page 119.

22002 : Control version

Used in: **Wire (custom interfaces)**

Definition: **22002**
 1

From control definition. See **Control definition: Control Model page** on page 119.

| Position | Description | Type | SBL command |
|----------|-----------------------|------|-------------|
| 1 | Control version (0–3) | int | none |

22003 : Piece name

Used in: **Wire (custom interfaces)**

Definition: **22003**
 string

This is only used by the Agievision interface. It is always 0 if the TECH library interface is selected. See **Machine group properties: Piece Details tab** on page 134.

| Position | Description | Type | SBL command |
|----------|-------------|--------|-------------------|
| 1 | Piece name | string | ID_NAMEOBJ |

22004 : Piece material

Used in: **Wire (custom interfaces)**

Definition: **22004**
 string

See **Machine group properties: Piece Details tab** on page 134.

| Position | Description | Type | SBL command |
|----------|---------------|--------|--------------------|
| 1 | Material code | string | ID_MATERIAL |

This is output as a numeric code, padded with leading zeros to 4 places. The table below lists the possible values. This is only used by the Agievision interface. It is always 0 if the TECH library interface is selected.

Table 2: Piece material codes

| Value | Material |
|-------|----------------|
| 0001 | Cold Die Steel |

Table 2: Piece material codes

| Value | Material |
|-------|-----------------------------------|
| 0011 | Electrolytic Cu |
| 0021 | Graphite 1 (grain < 5µm) |
| 0031 | Tung.carbide 85 WC\15Co |
| 0041 | Aluminum |
| 0051 | Brass |
| 0061 | Sialon |
| 0071 | PCD 002 (grain 2µm) |
| 0081 | Graphite 2 (grain 5..10µm) |
| 0091 | Graphite 3 (grain > 10µm) |
| 0101 | PCD 010 (grain 10µm) |
| 0111 | PCD 025 (grain 25µm) |
| 0121 | PCD-CTC002 |
| 0122 | PCD-CTB002 |
| 0123 | PCD-CTB010 |
| 0124 | PCD-CTB025 |
| 0125 | PCD-CTH025 |
| 0126 | PCD-CTM302 |
| 0131 | PCD-Compax 1300 |
| 0132 | PCD-Compax 1500 |
| 0133 | PCD-Compax 1600 |
| 0141 | PCD C30X |
| 0151 | PCB AMB90 |
| 0152 | PCB DBW85 |
| 0153 | PCB DBA80 |
| 0154 | PCB DBC50 |
| 0155 | PCB DBN45 |
| 0161 | PCB BZN 8200 |
| 0162 | PCB BZN 6000 |
| 0171 | PCB N90 |
| 0181 | CPM 10V (powder metallurgy steel) |

22005 : Piece wire name

Used in: **Wire (custom interfaces)**


Definition: **22005**
 string


This is only used by the Agievision interface. It is always 0 if the TECH library interface is selected. See **Machine group properties: Piece Details tab** on page 134.

| Position | Description | Type | SBL command |
|----------|-----------------|--------|-------------|
| 1 | Piece wire name | string | ID_THREAD |

Control definition: Control Model page

The following pictures show the **Control Model** page for both the Agievision and TECH interfaces.





The text string for the **Machine model** is output with the 22001 line. Note that for the Makino and Mitsubishi machines, the **Control version** option is disabled. This is always output as **0** on the 22002 line.

Agievision parameters

The Agievision interface introduced with Mastercam X4 includes many custom dialog boxes that mimic the look and feel of the Agievision control.

- Parameters 22051–22100 are used to output these values.
- The Agievision interface also uses 22001–22005; these are documented in [Common parameters](#) on page 117.



IMPORTANT: This represents a significant change from how Agie data was written out by the Agie C-Hook used in Mastercam X3. The C-Hook wrote the data to a separate .ADT file to be read by the post, instead of the 22000 parameters. Posts written for the new Agievision interface therefore need to be completely different.

You can see pictures of all the dialog boxes annotated with the parameter numbers beginning with [Machine group properties: Piece Setup tab](#) on page 133.

22051 : Piece quality target

Used in: **Wire (Agie interface)**

Definition: **22051**
string (piece quality target)

This parameter writes the piece quality target as a string (machining quality targets are written in lines 22055–22057). The numeric real values for Ra, Tf, and Tkm that correspond to this setting are written on line 22058, parameters 1–3.

See [Machine group properties: Piece Details tab](#) on page 134.

22052 : Machining strategy

Used in: **Wire (Agie interface)**

Definition: **22052**
string

A one- or two-letter code is written to the NCI for each strategy. See [Machine group properties: Piece Details tab](#) on page 134.

| Position | Description | Type | SBL command |
|----------|---------------|--------|-------------|
| 1 | Strategy code | string | ID_STRATEGY |

Table 3: Machining strategy codes

| Code Strategy | |
|---------------|-------------|
| A | Machine |
| E | Early |
| L | Late |
| W | Piece |
| EW | Early Piece |
| LW | Late Piece |
| WE | Piece Early |

Table 3: Machining strategy codes

| Code Strategy | |
|---------------|------------|
| WL | Piece Late |

22053 : Piece setup

Used in: **Wire (Agie interface)**

Definition: **22053**
1 2 3 4 5 6 7 8 9

See **Machine group properties: Piece Setup tab** on page 133. (**Machine group properties: Piece Setup tab** on page 133 also lists the pre-defined variables used for the piece dimensions).

| Position | Description | Type | SBL command |
|----------|------------------------------|------|--------------------|
| 1 | Piece reference position (X) | real | ID_POSX |
| 2 | Piece reference position (Y) | real | ID_POSY |
| 3 | Piece reference position (Z) | real | ID_POSZ |
| 4 | Piece reference position (C) | real | ID_ROTATION |
| 5 | Edge position (X) | real | ID_POSPOSX |
| 6 | Edge position (Y) | real | ID_POSPOSY |
| 7 | Edge position (Z) | real | ID_POSPOSZ |
| 8 | Security level | real | ID_VALSECP |
| 9 | Return level | real | ID_VALRETP |

22054: Machining name

Used in: **Wire (Agie interface)**

Definition: **22054**
string

See **Wirepath parameters: Machining page** on page 134.

| Position | Description | Type | SBL command |
|----------|----------------|--------|-----------------------|
| 1 | Machining name | string | Create working |

22055: Machining quality target (No Core Group, Collar LC1 wirepaths)

Used in: **Wire (Agie interface)**

Definition: **22055**
string (machining quality target)

This parameter outputs the machining quality target as a string. Lines 22055, 22056, and 22057 all output the machining quality target, but for different types of wirepaths.

The numeric real values for Ra, Tf, and Tkm that correspond to this setting are output on line 22058, parameters 6–8.

See [Wirepath parameters: Machining page](#) on page 134.

| Position | Description | Type | SBL command |
|----------|--------------------------|--------|-------------|
| 1 | Machining quality target | string | ID_QUALITY |

22056: Machining quality target (No Core Rough, Collar LC2 wirepaths)

Used in: **Wire (Agie interface)**

Definition: **22056**
string (machining quality target)

This parameter outputs the machining quality target as a string. Lines 22055, 22056, and 22057 all output the machining quality target, but for different types of wirepaths.

The numeric real values for Ra, Tf, and Tkm that correspond to this setting are output on line 22058, parameters 11–13.

See [Wirepath parameters: Machining page](#) on page 134.

| Position | Description | Type | SBL command |
|----------|--------------------------|--------|-------------|
| 1 | Machining quality target | string | ID_QUALITY |

22057: Machining quality target (No Core Finish, Collar LC3, Contour, and 4-axis wirepaths)

Used in: **Wire (Agie interface)**

Definition: **22057**
string (machining quality target)

This parameter outputs the machining quality target as a string. Lines 22055, 22056, and 22057 all output the machining quality target, but for different types of wirepaths.

The numeric real values for Ra, Tf, and Tkm that correspond to this setting are output on line 22058, parameters 16–18.

See [Wirepath parameters: Machining page](#) on page 134.

| Position | Description | Type | SBL command |
|----------|--------------------------|--------|-------------|
| 1 | Machining quality target | string | ID_QUALITY |

22058: Quality info

Used in: **Wire (Agie interface)**

Definition: **22058**
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

This line has 4 sets of 5 parameters, one for each of 4 quality targets. See [Machine group properties: Piece Details tab](#) on page 134 and [Wirepath parameters: Machining page](#) on page 134.

| Position | Description | Type | SBL command |
|----------|--------------------------|------|-------------|
| 1 | Piece quality (22051)—Ra | real | none |

| Position | Description | Type | SBL command |
|----------|---|------|-------------|
| 2 | Piece quality (22051)—Tf | real | none |
| 3 | Piece quality (22051)—Tkm | real | none |
| 4 | Speed/quality options (22051): <ul style="list-style-type: none"> ▪ 0 = neither ▪ 1 = Speed ▪ 2 = Quality ▪ 3 = both | int | none |
| 5 | Create quality checkbox (22051). See Wirepath parameters: User Tech (Technology Database) dialog box for parameters 4 & 5. | int | none |
| 6 | Quality LC1 (22055)—Ra | real | none |
| 7 | Quality LC1 (22055)—Tf | real | none |
| 8 | Quality LC1 (22055)—Tkm | real | none |
| 9 | Speed/quality options (Quality LC1 :22055): <ul style="list-style-type: none"> ▪ 0 = neither ▪ 1 = Speed ▪ 2 = Quality ▪ 3 = both | int | none |
| 10 | Create quality checkbox (Quality LC1 : 22055). See Wirepath parameters: User Tech (Technology Database) dialog box for parameters 9 & 10. | int | none |
| 11 | Quality LC2 (22056)—Ra | real | none |
| 12 | Quality LC2 (22056)—Tf | real | none |
| 13 | Quality LC2 (22056)—Tkm | real | none |
| 14 | Speed/quality options (Quality LC2 :22056): <ul style="list-style-type: none"> ▪ 0 = neither ▪ 1 = Speed ▪ 2 = Quality ▪ 3 = both | int | none |
| 15 | Create quality checkbox (Quality LC2 : 22056). See Wirepath parameters: User Tech (Technology Database) dialog box for parameters 14 & 15. | int | none |
| 16 | Quality LC3 (22057)—Ra | real | none |
| 17 | Quality LC3 (22057)—Tf | real | none |
| 18 | Quality LC3 (22057)—Tkm | real | none |
| 19 | Speed/quality options (Quality LC3: 22057): <ul style="list-style-type: none"> ▪ 0 = neither ▪ 1 = Speed ▪ 2 = Quality ▪ 3 = both | int | none |

| Position | Description | Type | SBL command |
|----------|--|------|-------------|
| 20 | Create quality checkbox (Quality LC3: 22057). See Wirepath parameters: User Tech (Technology Database) dialog box for parameters 19 & 20. | int | none |

22059 : Machining wire name

Used in: **Wire (Agie interface)**

Definition: **22059**
 string

See **Wirepath parameters: Machining page** on page 134.

| Position | Description | Type | SBL command |
|----------|---------------------|--------|------------------|
| 1 | Machining wire name | string | ID_THREAD |

22060: Machining data

Used in: **Wire (Agie interface)**

Definition: **22060**
 1 2 3 4 5 6 7 8

See **Wirepath parameters: Machining page** on page 134.

| Position | Description | Type | SBL command |
|----------|------------------------|------|--------------------|
| 1 | Priority | int | ID_PRIORITY |
| 2 | Technological height | real | ID_HEIGHT |
| 3 | Machine reference (X+) | real | ID_POSX |
| 4 | Machine reference (Y+) | real | ID_POSY |
| 5 | Machine reference (Z) | real | ID_POSZ |
| 6 | Machine reference (A) | real | ID_POSA |
| 7 | Machine reference (B) | real | ID_POSB |
| 8 | Machine reference (C) | real | ID_ROTATION |

22061: Agie cut data

Used in: **Wire (Agie interface)**

Definition: **22061**
1 2 3 4 5 6 7 8 9 10 11 12

See [Wirepath parameters: Cut parameters page](#) on page 136.

| Position | Description | Type | SBL command |
|----------|---|-------------|--------------------------|
| 1 | Compensation: punch vs. die <ul style="list-style-type: none"> ▪ 0= punch ▪ 1 = die ▪ -1 = disabled (for example, an open chain) | int | ID_PUNCH |
| 2 | Compensation: left or right <ul style="list-style-type: none"> ▪ 0= left ▪ 1 = right ▪ -1 = disabled (for example, a closed chain) | int | ID_PUNCH |
| 3 | Has minimum Agievision radius been applied to the last cut ? | int | ID_RADIUSMINLA |
| 4 | <i>Not used</i> | <i>int</i> | |
| 5 | Reverse cut? | int | ID_REVCUT |
| 6 | The number of working steps without inversion. | int | ID_ASWITHOUT |
| 7 | Separation cut length | real | ID_SEPCUT |
| 8 | Separation cut clearance | real | ID_CLEARANCETRENN |
| 9 | Clearance distance between punch and die chains | real | ID_CLEARANCE |
| 10 | <i>Not used</i> | <i>int</i> | |
| 11 | <i>Not used</i> | <i>int</i> | |
| 12 | <i>Not used</i> | <i>real</i> | |

22062: Start point name

Used in: **Wire (Agie interface)**

Definition: **22062**
string

See [Wirepath parameters: Start Point page](#) on page 136.

| Position | Description | Type | SBL command |
|----------|------------------|--------|---------------|
| 1 | Start point name | string | ID_STP |

22063: Start point data

Used in: **Wire (Agie interface)**

Definition: **22063**
 1 2 3 4

See **Wirepath parameters: Start Point page** on page 136.

| Position | Description | Type | SBL command |
|----------|----------------------|------|--------------------|
| 1 | Start point (X) | real | ID_POSX |
| 2 | Start point (Y) | real | ID_POSY |
| 3 | Start point (Z) | real | ID_POSZ |
| 4 | Start point diameter | real | ID_DIAMETER |

22064: Entry data

Used in: **Wire (Agie interface)**

Definition: **22064**
 1 2 3 4 5 6 7 8

See **Wirepath parameters: Entry page** on page 137.

| Position | Description | Type | SBL command |
|----------|---|------|--------------------------|
| 1 | Entry position: <ul style="list-style-type: none"> ▪ 0= Beginning of element ▪ 1 = Middle of element ▪ 2 = End of element | int | ID_ENTRYTIPO |
| 2 | Type of entry: <ul style="list-style-type: none"> ▪ 0= Free ▪ 1 = Perpendicular ▪ 2 = Tangential | int | ID_ENTRYMODE |
| 3 | Contour separation distance | real | ID_GEOCOMTRENN |
| 4 | Entry distance | real | ID_COMMPOINTENTRY |
| 5 | Increment entries (increment distance for each working step) | real | ID_SETENTD |
| 6 | Entry dislocation (new entry distance from previous entry point) | real | ID_SETENTM |
| 7 | Entry "A" distance (deviation distance from start point to contour entry, in Y direction) | real | ID_SETENTA |
| 8 | Entry "B" distance (deviation distance from start point to contour entry, in X direction) | real | ID_SETENTB |

22065: Exit data

Used in: **Wire (Agie interface)**

Definition: **22065**
 1 2 3 4

See **Wirepath parameters: Exit page** on page 137.

| Position | Description | Type | SBL command |
|----------|--|------|-------------------------|
| 1 | Type of exit: <ul style="list-style-type: none"> ▪ 0= Free ▪ 1 = Perpendicular ▪ 2 = Tangential | int | ID_EXITMODE |
| 2 | Exit distance | real | ID_COMMPOINTEXIT |
| 3 | Exit "A" distance (deviation distance from contour exit, parallel to exit contour element) | real | ID_SETUSCA |
| 4 | Exit "B" distance (deviation distance from contour exit, perpendicular to exit contour element) | real | ID_SETUSCB |

22066: Taper thread data

Used in: **Wire (Agie interface)**

Definition: **22066**
 1 2 3 4 5 6 7

See **Wirepath parameters: Threading page** on page 138.

| Position | Description | Type | SBL command |
|----------|---------------------|------|--------------------|
| 1 | Taper thread (X) | real | ID_POSX |
| 2 | Taper thread (Y) | real | ID_POSY |
| 3 | Taper thread (Z) | real | ID_POSZ |
| 4 | Taper thread (Xs) | real | ID_POSX_S |
| 5 | Taper thread (Ys) | real | ID_POSY_S |
| 6 | Taper thread (Zs) | real | ID_POSZ_S |
| 7 | Start hole diameter | real | ID_DIAMETER |

22067: Taper data

Used in: **Wire (Agie interface)**

Definition: **22067**
 1 2 3 4 5 6

These parameters are only used for Contour wirepaths. See **Wirepath parameters: Taper page** on page 138.

| Position | Description | Type | SBL command |
|----------|---|------|---------------------|
| 1 | Taper type and direction: <ul style="list-style-type: none"> ▪ 0 = left taper (upper wire guide moves left) ▪ 1 = right taper (upper wire guide moves right) ▪ 2 = fixed taper (defined by the X and Y component fields) | int | ID_TAPERMODE |
| 2 | Taper (Z) | real | ID_POSZ |
| 3 | Taper angle; if taper type = 0, ID_TAPER is output as negative value, if taper type = 1, ID_TAPER is output as positive value. | real | ID_TAPER |
| 4 | Taper (X component) | real | ID_TAPER |
| 5 | Taper (Y component) | real | ID_TAPERP |
| 6 | Isoradius: <ul style="list-style-type: none"> ▪ 0 = Default (conical) ▪ 1 = Isoradius | int | none |

22068: Corner data

Used in: **Wire (Agie interface)**

Definition: **22068**
 1 2 3 4

See **Wirepath parameters: Corners page** on page 139.

| Position | Description | Type | SBL command |
|----------|---|------|-------------------|
| 1 | External corner type: <ul style="list-style-type: none"> ▪ 0 = Minimum radius ▪ 1 = Sharp-edged ▪ 2 = Fixed radius | int | ID_E_TYPE |
| 2 | External corner radius (for fixed-radius corners) | real | ID_E_VALUE |
| 3 | Internal corner type: <ul style="list-style-type: none"> ▪ 0 = Minimum radius ▪ 1 = Sharp-edged ▪ 2 = Fixed radius | int | ID_I_TYPE |
| 4 | Internal corner radius (for fixed-radius corners) | real | ID_I_VALUE |

22069: Attribute data

Used in: **Wire (Agie interface)**

Definition: **22069**
 1 2 3 4

See **Wirepath parameters: Attributes page** on page 139.

| Position | Description | Type | SBL command |
|----------|--|------------|--------------------|
| 1 | Piece difficulty level: <ul style="list-style-type: none"> ▪ 0 = Normal ▪ 1 = More difficult ▪ 2 = Still more difficult ▪ 3 = Most difficult Note: these are written to the NCI as 0–3, but are written to the SBL file as 1–4. | int | ID_WORKCOND |
| 2 | Trim cut security level increment | real | ID_DELTAPS |
| 3 | <i>Not used</i> | <i>int</i> | |

22070: Collar data

Used in: **Wire (Agie interface)**

Definition: **22070**
1 2 3 4 5

These parameters are used for collar operations only. Note that the quality setting parameters for LC1, LC2, and LC3 are output on line 22058. See **Wirepath parameters: Collar page** on page 140.

| Position | Description | Type | SBL command |
|----------|---|------|------------------|
| 1 | Type of collar: <ul style="list-style-type: none"> ▪ 0 = Conical section of wirepath opens to the top ▪ 1 = Conical section of wirepath opens to the bottom ▪ 2 = Conical sections of wirepath open to both the top and bottom | int | ID_COLLAR |
| 2 | Collar Z1 | real | ID_POSZ |
| 3 | Collar Alfa 1 (taper angle) | real | ID_TAPER |
| 4 | Collar Z2 | real | ID_POSZ |
| 5 | Collar Alfa 2 (taper angle) | real | ID_TAPER |

22071: Group name

Used in: **Wire (Agie interface)**

Definition: **22071**
string

This is used for No core and collar operations only. See **Wirepath parameters: Group page** on page 140.

| Position | Description | Type | SBL command |
|----------|-------------|--------|--------------------|
| 1 | Group name | string | CreateGroup |

22072: Group wire name

Used in: **Wire (Agie interface)**

Definition: **22072**
string

This is used for No core and collar operations only. See **Wirepath parameters: Group page** on page 140.

| Position | Description | Type | SBL command |
|----------|-----------------|--------|------------------|
| 1 | Group wire name | string | ID_THREAD |

22073: Group data


Used in: **Wire (Agie interface)**

Definition: **22073**
1 2 3 4 5 6 7


These parameters are used for No core and collar operations only. See **Wirepath parameters: Group page** on page 140.

| Position | Description | Type | SBL command |
|----------|--------------------------------------|------|--------------------|
| 1 | Erosion sequence priority for group. | int | ID_PRIORITY |
| 2 | Group machine reference (X) | real | ID_POSX |
| 3 | Group machine reference (Y) | real | ID_POSY |
| 4 | Group machine reference (Z) | real | ID_POSZ |
| 5 | Group machine reference (A) | real | ID_POSA |
| 6 | Group machine reference (B) | real | ID_POSB |
| 7 | Group machine reference (C) | real | ID_ROTATION |


Machine group properties: Piece Setup tab




Machine group properties: Piece Details tab



Wirepath parameters: Machining page



Wirepath parameters: User Tech (Technology Database) dialog box



Wirepath parameters: Cut parameters page

- Wirepath Type
- Machining
 - ✓ Cut Parameters
- Start Point
- Taper
- Corners
- Attributes
- Misc. Values
- Aux. Registers

Punch 22061:1

Die

Left 22061:2

Right

22061:3 Minimum Radius last work

22061:5 Reverse Cut

Separation Cut 22061:7

Separation Cut Clearance 22061:8

Clearance 22061:9

Working st. wo. Inversion 22061:6

Quick View Settings

Wire Dia:

Wirepath parameters: Start Point page


- Wirepath Type
- Group
- Rough
- Cut Parameters
- Start Point
- Entry
- Exit
- Threading
- Corners
- Attributes
- Misc. Values
- Aux. Registers
- Finish

Startpoint name

X 22063:1

Y 22063:2

Z 22063:3



Diameter 22063:4

Wirepath parameters: Entry page

- Wirepath Type
- Group
- Rough
- Cut Parameters
- Start Point
- Entry
- Exit
- Threading
- Corners
- Attributes
- Misc. Values
- Aux. Registers
- Finish

22064:1

Beginning of Element

Middle of Element

End of Element

22064:2

Free

Perpendicular

Tangential

Contour Separation

22064:3

Increment of Entries

22064:5

A:

22064:7

Entry -> Contour

22064:4

Entry Dislocation

22064:6

B:

22064:8

Wirepath parameters: Exit page

- Wirepath Type
- Group
- Rough
- Cut Parameters
- Start Point
- Entry
- Exit
- Threading
- Corners
- Attributes
- Misc. Values
- Aux. Registers
- Finish

22065:1

Free

Perpendicular

Tangential

Contour -> Exit

22065:2

A:

22065:3


B:


22065:4

Wirepath parameters: Threading page


Wirepath Type


- Group
- Rough
- Cut Parameters
- Start Point
 - Entry
 - Exit
 - Threading
- Corners
- Attributes
- Misc. Values
- Aux. Registers
- Finish





| | | | | | | |
|---|------|---------|--|----|-----|---------|
| X | 0.0 | 22066:1 | | Xs | 0.0 | 22066:4 |
| Y | 0.0 | 22066:2 | | Ys | 0.0 | 22066:5 |
| Z | -1.0 | 22066:3 | | Zs | 0.0 | 22066:6 |





Starhole Diameter 0.0 22066:7


Quick View Settings


Wire Dia: 0.009842


Wirepath parameters: Taper page

Wirepath Type

- Machining
- Cut Parameters
- Start Point
 - Entry
 - Exit
 - Threading
 - Taper
- Corners
- Attributes
- Misc. Values
- Aux. Registers







Z: 0.0 22067:2

Alfa: 0.0 22067:3

X Component: 0.0 22067:4

Y Component: 0.0 22067:5


Default 22067:6

Isoradius


Quick View Settings

Wire Dia: 0.007874

Wirepath parameters: Corners page



Wirepath parameters: Attributes page



Wirepath parameters: Group page

Wirepath Type

- Group
- Collar
- Cut Parameters
- Start Point
- Comers
- Attributes
- Misc. Values
- Aux. Registers

Group

Wire
 [Tp-Gamma, 0.250]

Priority

Distance piece/group reference --> Machine reference

| | | | | | | | |
|----|----------------------------------|--------------------------------------|----------------------------------|--|---|----------------------------------|--------------------------------------|
| X+ | <input type="text" value="0.0"/> | <input type="text" value="22073:2"/> | | | A | <input type="text" value="0.0"/> | <input type="text" value="22073:5"/> |
| Y+ | <input type="text" value="0.0"/> | <input type="text" value="22073:3"/> | <input type="button" value="↕"/> | | B | <input type="text" value="0.0"/> | <input type="text" value="22073:6"/> |
| Z | <input type="text" value="0.0"/> | <input type="text" value="22073:4"/> | | | C | <input type="text" value="0.0"/> | <input type="text" value="22073:7"/> |

Quick View Settings

Wire Dia:

Wirepath parameters: Collar page

22070:1

(value = 0)

(value = 1)

(value = 2)

Quality LC1
 [1.500, 1.000, 1.000]

Quality LC2
 [1.500, 1.000, 1.000]

Quality LC3
 [1.500, 1.000, 1.000]

Z1: Z2:

Alfa1 Alfa2

TECH library parameters

NCI lines 22001–22113 are output for each roughing cut and skim pass, for both primary and taper cuts. The data that you see and select in the **Technology Database dialog box** is read from the XML data in the .TECH file; not all of it is visible in the dialog box.

22101: Machine string

Used in: **Wire (TECH interface)**

Definition: **22101**
 string

Machine string; used to identify the library.

22102: Control string

Used in: **Wire (TECH interface)**

Definition: **22102**
 string

Control string; used to identify the library.

22103: Inch/metric

Used in: **Wire (TECH interface)**

Definition: **22103**
 1

Units integer. 0 = inch, 1 = metric.

22104: Power library comment

Used in: **Wire (TECH interface)**

Definition: **22104**
 string

Power library comment. This is a single string that is used for the entire library.

22105: Quality description/label

Used in: **Wire (TECH interface)**

Definition: **22105**
 string

Quality description/label. This is a comment that applies to the individual pass.

22106: Machining condition code

Used in: **Wire (TECH interface)**

Definition: **22106**
 string

Machining condition code. This is output as a string, although it only contains numeric data. This is also output with the tool change lines (NCI 1000/1001/1002) as the ccode\$ parameter.

22107: Piece thickness*Used in:* **Wire (TECH interface)***Definition:* **22107**
 1 2 3 4 5 6

This line consists of a string of 6 numeric values:

- | | |
|---|---|
| 1 | Minimum thickness of primary piece. |
| 2 | Maximum thickness of primary piece. Note that not all parts will have different values for maximum and minimum thickness; in these cases, a single thickness value will be output in both places. |
| 3 | Primary Ra. If the selected Finish (Ra) is a range of values (see Technology Database dialog box on page 143), the value output with this parameter will be the average. |
| 4 | Minimum thickness of taper piece. |
| 5 | Maximum thickness of taper piece; see note for parameter 2. |
| 6 | Taper Ra. If the selected Finish (Ra) is a range of values (see Technology Database dialog box on page 143), the value output with this parameter will be the average. |

22108: Method for primary cuts*Used in:* **Wire (TECH interface)***Definition:* **22108**
 stringThe class **Method** for primary cuts.**22109: Method for taper cuts***Used in:* **Wire (TECH interface)***Definition:* **22109**
 stringThe class **Method** for taper cuts.**22110, 22111: Miscellaneous file paths***Used in:* **Wire (TECH interface)***Definition:* **22110 / 22111**
 string

Miscellaneous file paths (if any). These are read directly from the .TECH file.

22112: Finish (Ra) for primary cuts*Used in:* **Wire (TECH interface)***Definition:* **22112**
 string**Finish (Ra)** string for primary cuts.

22113: Finish (Ra) for taper cuts

Used in: **Wire (TECH interface)**

Definition: **22113**
string

Finish (Ra) string for taper cuts.

Technology Database dialog box

The screenshot shows the Technology Database dialog box with the following sections:

- Technology library:** C:\Documents and Settings\All Users\Documents\shared mcam5\WIRE\POWER\MAKINO DUO-VER6-INCH-V GUIDE.TECH
- Library identifier:**
 - Machine: DU043,DU064 **22101**
 - Control: Generic Makino **22102**
 - Units: Inch **22103**
- Work settings:**
 - Wire size: 0.006
 - Wire material: BS **22005**
 - Piece material: St **22004**
 - Piece thickness: 0.8 **22107**
 - Method: **22108, 22109** Both Away Precision
- Pass data:**

22106


| Pass | Power | Offset | Feed | Register |
|---------|--------|--------|-------|----------|
| A | ----- | ----- | ----- | ----- |
| Rough | (1056) | 0.0055 | 0.00 | 1 |
| Skim #1 | (1555) | 0.0036 | 0.00 | 2 |
| Skim #2 | (1556) | 0.0030 | 0.00 | 3 |
| Skim #3 | ----- | ----- | ----- | ----- |
| Skim #4 | ----- | ----- | ----- | ----- |
| Skim #5 | ----- | ----- | ----- | ----- |
| Skim #6 | ----- | ----- | ----- | ----- |
| Skim #7 | ----- | ----- | ----- | ----- |
| Skim #8 | ----- | ----- | ----- | ----- |
- Description:** Finish 45 **22105**
- Selector:**
 - Finish (Ra): 50~55 **22112, 22113**
 - Sequence: Rough & 2 skim(s)

Buttons at the bottom: [Checkmark] [X] [Question mark]

Validating the post for custom interfaces

Mastercam X4 introduced new validation routines designed to ensure that the post selected for the wire machine definition has been properly configured to work with the custom interface.

The Wire control definition includes a new **Control Model** page:



Selecting one of the machines from the **Machine model** list is what activates the custom interface.

- Select one of the Agie machines to enable the Agievision interface.
- Select the Makino or Mitsubishi machine to enable the TECH library interface.

The **Machine model** sets a new predefined variable, **controldefault\$**.

- Selecting **Generic** sets **controldefault\$** = 0. No custom interface will be enabled with this option.
- The 11 different Agie models set **controldefault\$** equal to a value from 1–11.

In the Agievision post, you will see this line:

```
sx_nci_default$ : "1.11" #Enable posting for integrated Agievision
```

MP uses this string to construct a range of valid values (in this case, 1 through 11) that are used to validate **controldefault\$**. So if the **Generic** machine model is selected in the control definition, **controldefault\$** will equal 0 and an error message will be generated, because 0 is not included in the range of valid values.

In this way, the single Agievision post can be used with any of the 11 Agie models.

- You can limit the range of valid models by adjusting the value of **sx_nci_default\$**.
- You can implement model-specific customizations by testing for the value of **controldefault\$**.

For the Makino and Mitsubishi machines, there is only a single **Machine model**, so when you select one of these machines, the **Control version** option is disabled. This is always output as 0 on the 22002 line.

- For the Makino, **sx_nci_default\$** = 100.100
- For the Mitsubishi, **sx_nci_default\$** = 50.50



NOTE: The text of the **Machine model** string is also available directly as a string parameter, **22001**.
